

Status of River Breakages Along River Shabelle, Somalia February 2020

Region	District	Settlement	Latitude	Longitude	Comments	Status	Length (m)	Image Date	Riverbank side facing downstream
Shabelle Lower	Kurtunwaarey	Towfiik	1.656	44.263	Current images are required to assess this site. Most current available image is of June 2018. The site is considered closed.	Co	0	21-Jun-18	Left
Shabelle Lower	Kurtunwaarey	Towfiik	1.65684	44.26878	Current images are required to assess this site. Most current available image is of 21 June 2018. The site was closed using sandbags in 2017.	Cs	0	21-Jun-18	Left
Shabelle Lower	Kurtunwaarey	Garas-Baxaar	1.617490946	44.21676313	There are no current images available to make an assessment for this site. Most up-to-date image is 21 June 2018.	Cs	0	21-Jun-18	Left
Shabelle Lower	Kurtunwaarey	Towfiik	1.656948898	44.26818296	Current images are required to assess this site. Most current available image is of 21 June 2018. The site was closed using sandbags in 2017.	Cs	0	21-Jun-18	Left
Shabelle Lower	Kurtunwaarey	Towfiik	1.657568983	44.26771592	Current images are required to assess this site. Most current available image is of 21 June 2018. The site was closed using sandbags in 2017.	Cs	0	21-Jun-18	Right
Shabelle Lower	Kurtunwaarey	Towfiik	1.65721485	44.26620971	Current images are required to assess this site. Most current available image is of 21 June 2018. The site was closed using sandbags in 2017.	Cs	0	21-Jun-18	Left
Shabelle Lower	Kurtunwaarey	Dhaayaney	1.656936089	44.26581791	Current images are required to assess this site. Most current available image is of 21 June 2018. The site was closed using sandbags in 2017.	Cs	0	21-Jun-18	Left
Shabelle Lower	Kurtunwaarey	Dhaayaney	1.656628829	44.26348099	Current images are required to assess this site. Most current available image is of 21 June 2018. The site was closed using sandbags in 2017.	Cs	0	21-Jun-18	Right
Shabelle Lower	Kurtunwaarey	Dhaayaney	1.646525	44.2441	Current images are required to assess this site. Most current available image is of June 2018. The site is considered closed.	Cm	0	24-Jun-18	Right
Shabelle Lower	Kurtunwaarey	Towfiik	1.65	44.255	Current images are required to assess this site. Most current available image is of June 2018. The site is considered closed.	Cm	0	24-Jun-18	Right
Shabelle Lower	Kurtunwaarey	Aflow	1.654119554	44.28027292	There are no current images available to make an assessment for this site. Most up-to-date image is 24 June 2018.	P	0	24-Jun-18	Right
Shabelle Lower	Kurtunwaarey	Uraanurow	1.655299359	44.28569688	There are no current images available to make an assessment for this site. Most up-to-date image is 24 June 2018.	P	0	24-Jun-18	Left
Shabelle Lower	Kurtunwaarey	Uraanurow	1.655350299	44.28339649	There are no current images available to make an assessment for this site. Most up-to-date image is 24 June 2018.	P	0	24-Jun-18	Left
Hiraan	Bulo Burto	Cadey-Jameeco	4.173041197	45.4317422	There are no current images available to make an assessment for this site. Most up-to-date image is 08September2018.	O	8	8-Sep-18	Right
Hiraan	Bulo Burto	Cadey-Jameeco	4.187655599	45.42113199	There are no current images available to make an assessment for this site. Most up-to-date image is 08September2018.	O	9	8-Sep-18	Right
Hiraan	Bulo Burto	Bur Dooxo	4.19133653	45.42050798	There are no current images available to make an assessment for this site. Most up-to-date image is 08September2018.	O	7	8-Sep-18	Left
Hiraan	Bulo Burto	Bur Dooxo	4.196541084	45.41687695	There are no current images available to make an assessment for this site. Most up-to-date image is 08September2018.	O	5	8-Sep-18	Left
Hiraan	Bulo Burto	Ilimey	4.176274309	45.43013192	There are no current images available to make an assessment for this site. Most up-to-date image is 08September2018.	P	0	8-Sep-18	Left
Hiraan	Bulo Burto	Doonkaxare	4.160485527	45.46100414	There are no current images available to make an assessment for this site. Most up-to-date image is 08September2018.	P	0	8-Sep-18	Right
Hiraan	Bulo Burto	Ilimey	4.170252303	45.4371815	There are no current images available to make an assessment for this site. Most up-to-date image is 08September2018.	P	0	8-Sep-18	Left
Hiraan	Bulo Burto	Cadey-Jameeco	4.171482594	45.43501386	There are no current images available to make an assessment for this site. Most up-to-date image is 08September2018.	P	0	8-Sep-18	Right
Hiraan	Bulo Burto	Cadey-Jameeco	4.178207083	45.42608245	There are no current images available to make an assessment for this site. Most up-to-date image is 08September2018.	P	0	8-Sep-18	Right
Hiraan	Bulo Burto	Cadey-Jameeco	4.201136224	45.40664264	There are no current images available to make an assessment for this site. Most up-to-date image is 08September2018.	P	0	8-Sep-18	Right
Hiraan	Bulo Burto	Buscad	4.228122884	45.41663457	There are no current images available to make an assessment for this site. Most up-to-date image is 08September2018.	P	0	8-Sep-18	Right
Hiraan	Bulo Burto	Dhagaxyo-weyne	4.290044982	45.38855696	There are no current images available to make an assessment for this site. Most up-to-date image is 07September2018.	P	0	8-Sep-18	Right
Hiraan	Bulo Burto	Dhagaxyo-Weyne	4.290784	45.389053	There are no current images available to make an assessment for this site. Most up-to-date image is 08 September 2018.	P	0	8-Sep-18	Left
Hiraan	Bulo Burto	Dhagaxyo-Weyne	4.290674979	45.39202751	There are no current images available to make an assessment for this site. Most up-to-date image is 07September2018.	POF	0	8-Sep-18	Left
Shabelle Middle	Jowhar	Diinlaawe	3.0374	45.50132	There are no current images available to make an assessment for this site. Most up-to-date image is 16September2018	O	11	16-Sep-18	Right
Shabelle Middle	Jowhar	Diinlaawe	3.03667	45.50191	There are no current images available to make an assessment for this site. Most up-to-date image is 16September2018	O	5	16-Sep-18	Left
Shabelle Middle	Jowhar	Diinlaawe	3.043009	45.517437	There are no current images available to make an assessment for this site. Most up-to-date image is 16September2018.	P	0	16-Sep-18	Left
Shabelle Middle	Jowhar	Diinlaawe	3.04112	45.50902	16September2018. A current image is needed for further assessment. Waters originating from this part are causing floods into the nearby farms.	P	0	16-Sep-18	Left
Shabelle Lower	Afgooye	Berta Shegalka	2.190996	45.177888	There are no current images available to make an assessment for this site. Most up-to-date image is 18 September 2019.	PO	0	18-Sep-18	Left
Hiraan	Belet Weyne	Dolo madow	4.86277	45.10123	There are no current images available to make an assessment for this site. Most up-to-date image is 21 November 2018.	O	3	21-Nov-18	Right
Hiraan	Belet Weyne	Dolo madow	4.86339	45.10154	There are no current images available to make an assessment for this site. Most up-to-date image is 21 November 2018.	POF	0	21-Nov-18	Left
Hiraan	Belet Weyne	Dolo madow	4.86356	45.10662	There are no current images available to make an assessment for this site. Most up-to-date image is 21 November 2018.	POF	0	21-Nov-18	Right
Hiraan	Belet Weyne	Dolo madow	4.864157	45.105575	There are no current images available to make an assessment for this site. Most up-to-date image is 21 November 2018.	POF	0	21-Nov-18	Left
Shabelle Lower	Kurtunwaarey	Uro Urow	1.645879506	44.34311489	There are no current images available to make an assessment for this site. Most up-to-date image is 26 November 2018.	Cs	0	26-Nov-18	Left
Shabelle Lower	Kurtunwaarey	Uro Urow	1.646848839	44.34653273	There are no current images available to make an assessment for this site. Most up-to-date image is 26 November 2018.	Cs	0	26-Nov-18	Left
Shabelle Lower	Kurtunwaarey	Uraanurow	1.645755963	44.34261101	There are no current images available to make an assessment for this site. Most up-to-date image is 26 November 2018.	Cs	0	26-Nov-18	Right
Hiraan	Belet Weyne	Dharkeynley	4.7993	45.18549	There are no current images available to make an assessment for this site. Most up-to-date image is 16 January 2019.	Cm	0	16-Jan-19	Left
Hiraan	Belet Weyne	Qooqane	4.854544027	45.16344449	There are no current images available to make an assessment for this site. Most up-to-date image is 16 January 2019.	POF	0	16-Jan-19	Left
Hiraan	Belet Weyne	Qooqane	4.849706905	45.17107978	There are no current images available to make an assessment for this site. Most up-to-date image is 16 January 2019.	POF	0	16-Jan-19	Left
Hiraan	Belet Weyne	Bacadley	4.84899	45.17055	There are no current images available to make an assessment for this site. Most up-to-date image is 16 January 2019.	POF	0	16-Jan-19	Right
Hiraan	Belet Weyne	Jiliqily	4.401757	45.328791	There are no current images available to make an assessment for this site. Most up-to-date image is 06 February 2019.	Co	0	6-Feb-19	Left
Hiraan	Belet Weyne	Goley	4.402807912	45.32396035	There are no current images available to make an assessment for this site. Most up-to-date image is 06 February 2019.	Co	0	6-Feb-19	Right
Hiraan	Belet Weyne	Goley	4.401543246	45.32714723	There are no current images available to make an assessment for this site. Most up-to-date image is 06 February 2019.	Co	0	6-Feb-19	Left
Hiraan	Belet Weyne	Dolo Yaabeen	4.410434	45.321712	There are no current images available to make an assessment for this site. Most up-to-date image is 06 February 2019.	P	0	6-Feb-19	Right
Shabelle Lower	Afgooye	Raqeyle	2.03909	44.86782	Image of 20 October 2019. A sandbag intervention had been implemented in July 2019. Vegetation cover hinders a more accurate assessment of the site.	O	4	8-Feb-19	Left
Hiraan	Jalalaqsi	Bacadley	3.29998	45.56729	There is no current image to make an assessment for this site. Most current image is of 25 February 2019.	Cm	0	25-Feb-19	Right

Hiraan	Jalalaqsi	Bacadley	3.298423	45.566164	There is no current image to make an assessment for this site. Most current image is of 25 February 2019.	P	0	25-Feb-19	Left
Hiraan	Jalalaqsi	Bacadley	3.293299	45.56666	There is no current image to make an assessment for this site. Most current image is of 25 February 2019.	POf	0	25-Feb-19	Left
Hiraan	Jalalaqsi	Waasame	3.312613	45.572763	There are no current images available to make an assessment for this site. Most up-to-date image is 25 February 2019.	POf	0	25-Feb-19	Left
Hiraan	Jalalaqsi	Bacadley	3.29097	45.56707	There is no current image to make an assessment for this site. Most current image is of 25 February 2019.	POf	0	25-Feb-19	Right
Hiraan	Jalalaqsi	Bacadley	3.30362	45.57056	There are no current images available to make an assessment for this site. Most up-to-date image is 25 February 2019.	POf	0	25-Feb-19	Right
Hiraan	Belet Weyne	Dolo Yaabeen	4.410975	45.320448	There are no current images available to make an assessment for this site. Most up-to-date image is 27 February 2019.	Cm	0	27-Feb-19	Right
Hiraan	Belet Weyne	Dolo Yaabeen	4.416446	45.319478	Current images are required to assess this site. Most current available image is of February 2019.	P	0	27-Feb-19	Left
Shabelle Middle	Balad	Xanooleey	2.62569	45.507332	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	Cm	0	28-Feb-19	Right
Shabelle Middle	Balad	Balad	2.681937	45.507466	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	Cm	0	28-Feb-19	Right
Shabelle Middle	Balad	Mandheere	2.688100794	45.51179197	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019. Succeeding image of January 2020 is too cloudy.	Cm	0	28-Feb-19	Left
Shabelle Middle	Balad	Maagey	2.637563819	45.51095946	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	Cm	0	28-Feb-19	LeftRight
Shabelle Middle	Balad	Maagey	2.63236	45.51187	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	Cm	0	28-Feb-19	Left
Shabelle Middle	Balad	Gaashaanle	2.667474	45.506777	There are no current images available to make an assessment for this site. Most up-to-date image is 02 February 2019.	Co	0	28-Feb-19	Right
Shabelle Middle	Balad	Gaashaanle	2.623004	45.508575	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	Co	0	28-Feb-19	Left
Shabelle Middle	Balad	Balad	2.68074	45.50909	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	Co	0	28-Feb-19	Left
Shabelle Middle	Balad	Mandheere	2.683305	45.510016	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	Co	0	28-Feb-19	Right
Shabelle Middle	Balad	Mandheere	2.62101	45.51021	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	Co	0	28-Feb-19	Left
Shabelle Middle	Balad	Muukay	2.63885	45.511587	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	Co	0	28-Feb-19	Right
Shabelle Middle	Balad	Deymosame	2.668718	45.506401	There are no current images available to make an assessment for this site. Most up-to-date image is 02 February 2019.	Co	0	28-Feb-19	Left
Shabelle Middle	Balad	Maagey	2.635305346	45.51106856	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	Co	0	28-Feb-19	Left
Shabelle Middle	Balad	Deymosame	2.62915	45.50696	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	Cs	0	28-Feb-19	Left
Shabelle Middle	Balad	Bardheere	2.676961	45.50834	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	Cs	0	28-Feb-19	Left
Shabelle Middle	Balad	Muukay	2.636541	45.509625	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	Cs	0	28-Feb-19	Right
Shabelle Middle	Balad	Gaashaanle	2.644421	45.507754	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	O	26	28-Feb-19	Left
Shabelle Middle	Balad	Boodaal	2.680159	45.506744	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	P	0	28-Feb-19	Right
Shabelle Middle	Balad	Muukay	2.633531	45.512868	There are no current images available to make an assessment for this site. Most up-to-date image is 02 February 2019.	P	0	28-Feb-19	Left
Shabelle Middle	Balad	Balad	2.623274	45.505833	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	P	0	28-Feb-19	Right
Shabelle Middle	Balad	Maagey	2.63227739	45.51253478	There are no current images available to make an assessment for this site. Most up-to-date image is 28 February 2019.	P	0	28-Feb-19	Left
Shabelle Middle	Balad	Farbaraako	2.65781	45.4992	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	Cm	0	2-Mar-19	Left
Shabelle Middle	Balad	Bacadley	2.65631	45.496805	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	Cm	0	2-Mar-19	Right
Shabelle Middle	Balad	Bacadley	2.658143893	45.49905986	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	Cm	0	2-Mar-19	Right
Shabelle Middle	Balad	Tuugaarey	2.667692	45.505094	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	Co	0	2-Mar-19	Left
Shabelle Middle	Balad	Muukay	2.674155	45.505225	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	Co	0	2-Mar-19	Right
Shabelle Middle	Balad	Baqdaad	2.645168	45.505736	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	Co	0	2-Mar-19	Left
Shabelle Middle	Balad	Baqdaad	2.644827	45.50591	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	Co	0	2-Mar-19	Right
Shabelle Middle	Balad	Moyka	2.62843	45.51106	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	Co	0	2-Mar-19	Right
Shabelle Middle	Balad	Tuugaarey	2.660051	45.499357	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	Co	0	2-Mar-19	Right
Shabelle Middle	Balad	Gaashaanle	2.67379	45.50334	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	Co	0	2-Mar-19	Right
Shabelle Lower	Afgooye	Jambaluul	2.183465	45.155597	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	Cs	0	2-Mar-19	Right
Shabelle Middle	Balad	Boodal	2.64388	45.50145	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	Cs	0	2-Mar-19	Right
Shabelle Middle	Jowhar	Diinlaawe	3.03197	45.50265	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	O	5	2-Mar-19	Right
Shabelle Lower	Afgooye	Jambaluul	2.181747	45.155468	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	P	0	2-Mar-19	Left
Shabelle Middle	Balad	Balad	2.62679	45.51108	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	P	0	2-Mar-19	Left
Shabelle Middle	Balad	Bacadley	2.65775	45.49601	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	P	0	2-Mar-19	Right
Shabelle Middle	Balad	Bacadley	2.65819	45.49646	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	P	0	2-Mar-19	Right
Shabelle Middle	Balad	Tuugaarey	2.660882	45.500406	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	P	0	2-Mar-19	Left
Hiraan	Belet Weyne	Doolo Qoyan	4.426926	45.310309	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	P	0	2-Mar-19	Left
Hiraan	Belet Weyne	Doolo Qoyan	4.426651998	45.30871273	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	P	0	2-Mar-19	Right
Shabelle Middle	Jowhar	Diinlaawe	3.04268	45.50342	There are no current images available to make an assessment for this site. Most up-to-date image is 02 March 2019.	P	0	2-Mar-19	Right
Hiraan	Jalalaqsi	Buulo Cigalle	3.326336	45.571491	There are no current images available to make an assessment for this site. Most up-to-date image is 16 March 2019.	POf	0	16-Mar-19	Left
Hiraan	Jalalaqsi	Qurac-Jafle	3.330674	45.574128	There are no current images available to make an assessment for this site. Most up-to-date image is 16 March 2019.	POf	0	16-Mar-19	Left

Hiraan	Bulo Burto	Bulo Boorey	4.156128071	45.4634206	There are no current images available to make an assessment for this site. Most up-to-date image is 29 March 2019.	POf	0	29-Mar-19	Left
Shabelle Middle	Jowhar	Sabuun	2.891587	45.547822	up-to-date image is 30 March 2019. Succeeding images of October 2019 and December 2019 are too cloudy to carry out any assessment.	P	0	30-Mar-19	Left
Hiraan	Bulo Burto	Caaqoboy	4.271769	45.397796	There are no current images available to make an assessment for this site. Most up-to-date image is 23 April 2019.	P	0	23-Apr-19	Right
Shabelle Middle	Jowhar	Hurway	3.130318	45.552159	There is no current image to make an assessment for this site. Most current image is of 25 April 2019.	Cm	0	25-Apr-19	Left
Hiraan	Bulo Burto	Doonkaxare	4.151880408	45.47088928	up-to-date image is 28 April 2019. Succeeding image of 10 December 2019 is cloudy.	O	8	28-Apr-19	Right
Hiraan	Bulo Burto	Samataro	4.34845	45.37279	implemented in April 2019. Current images are needed. Most current image is of 01 May 2019.	Cm	0	1-May-19	Right
Hiraan	Belet Weyne	Dhaayow	4.37581	45.358361	Current images are required to assess this site. Most current available image is of May 2019. The site is considered closed.	Co	0	1-May-19	Left
Hiraan	Bulo Burto	Samataro	4.355426	45.370916	Current images are required to assess this site. Most current available image is of 01 May 2019. The site is a canal intake.	Co	0	1-May-19	Left
Shabelle Middle	Balad	Balcad	2.339377	45.379058	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	Co	0	1-May-19	Left
Hiraan	Belet Weyne	Dhaayow	4.362348	45.363067	There is no current image to make an assessment for this site. Most current image is of 01 May 2019.	Co	0	1-May-19	Right
Hiraan	Bulo Burto	Jameeco	4.310931	45.386441	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	Co	0	1-May-19	Left
Hiraan	Belet Weyne	Jiliqlay	4.403534	45.3297	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	Co	0	1-May-19	Left
Hiraan	Belet Weyne	Jiliqlay	4.402446	45.33206	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	Co	0	1-May-19	Left
Hiraan	Belet Weyne	Jiliqlay	4.393655	45.339851	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	Co	0	1-May-19	Right
Hiraan	Bulo Burto	Jameeco	4.301795	45.380257	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	O	14	1-May-19	Right
Hiraan	Bulo Burto	Jameeco	4.294688	45.385877	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	O	14	1-May-19	Right
Hiraan	Belet Weyne	Doolo Biciid	4.380925506	45.35102521	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	O	6	1-May-19	Right
Hiraan	Belet Weyne	Goonyaale	4.36412	45.36253	There is no current image to make an assessment for this site. Most current image is of 01 May 2019.	O	15	1-May-19	Right
Hiraan	Belet Weyne	Doolo biciid	4.38838	45.34882	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	O	5	1-May-19	Left
Hiraan	Belet Weyne	Doolo Biciid	4.38713	45.34928	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	O	5	1-May-19	Left
Hiraan	Bulo Burto	Samataro	4.348	45.372703	of recent floods at May 2019. Current images are required for more accurate assessment.	P	0	1-May-19	Right
Hiraan	Bulo Burto	Jameeco	4.313712	45.383149	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	P	0	1-May-19	Right
Hiraan	Bulo Burto	Jameeco	4.305152	45.381118	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	PO	0	1-May-19	Right
Hiraan	Belet Weyne	Doolo Biciid	4.377327	45.354274	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	PO	0	1-May-19	Right
Hiraan	Bulo Burto	Jameeco	4.300804253	45.38222348	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	POf	0	1-May-19	Right
Hiraan	Belet Weyne	Dhaayow	4.371943	45.361515	There are no current images available to make an assessment for this site. Most up-to-date image is 01 May 2019.	POf	0	1-May-19	Left
Shabelle Middle	Balad	Balcad	2.334562	45.373309	There are no current images available to make an assessment for this site. Most up-to-date image is 04 May 2019.	Cm	0	4-May-19	Left
Shabelle Middle	Balad	Muryaale	2.31281	45.36417	There are no current images available to make an assessment for this site. Most up-to-date image is 04 May 2019.	Co	0	4-May-19	Left
Shabelle Middle	Balad	Eladi Mir Mau	2.332501	45.380995	There are no current images available to make an assessment for this site. Most up-to-date image is 04 May 2019.	P	0	4-May-19	Left
Shabelle Middle	Balad	Eladi Mir Mau	2.329907926	45.37582591	There are no current images available to make an assessment for this site. Most up-to-date image is 04 May 2019.	PO	0	4-May-19	Left
Hiraan	Jalalaqsi	Bacadley	3.29617	45.56287	There is no current image to make an assessment for this site. Most current image is of 8 June 2019.	POf	0	8-Jun-19	Right
Shabelle Lower	Afgooye	Shukuroow	2.166287	45.138246	There are no current images available to make an assessment for this site. Most up-to-date image is 11 June 2019.	P	0	11-Jun-19	Left
Shabelle Lower	Afgooye	Buulo-Xaartooy	2.17338	45.146726	There are no current images available to make an assessment for this site. Most up-to-date image is 11 June 2019.	P	0	11-Jun-19	Left
Shabelle Middle	Balad	Boodal	2.614046	45.505828	There are no current images available to make an assessment for this site. Most up-to-date image is 23 June 2019.	Cm	0	23-Jun-19	Left
Shabelle Middle	Balad	Deymosame	2.608836	45.505137	There are no current images available to make an assessment for this site. Most up-to-date image is 29 June 2019.	Cm	0	29-Jun-19	Left
Shabelle Middle	Balad	Shanlow	2.536049	45.488106	There are no current images available to make an assessment for this site. Most up-to-date image is 29 June 2019.	Cm	0	29-Jun-19	Left
Shabelle Middle	Balad	Balad	2.61245	45.510473	There are no current images available to make an assessment for this site. Most up-to-date image is 29 June 2019.	Co	0	29-Jun-19	Left
Shabelle Middle	Balad	Shanlow	2.53888	45.48534	There are no current images available to make an assessment for this site. Most up-to-date image is 29 June 2019.	Co	0	29-Jun-19	Left
Shabelle Middle	Balad	Shanlow	2.533747	45.484973	There are no current images available to make an assessment for this site. Most up-to-date image is 29 June 2019.	Cs	0	29-Jun-19	Right
Shabelle Middle	Balad	Deymosame	2.609267	45.505484	There are no current images available to make an assessment for this site. Most up-to-date image is 29 June 2019.	P	0	29-Jun-19	Left
Shabelle Middle	Balad	Jameeco Misr	2.56004	45.48893	There are no current images available to make an assessment for this site. Most up-to-date image is 02 July 2019.	Co	0	2-Jul-19	Right
Shabelle Lower	Kurtunwaarey	Gorgaal	1.661295298	44.39128046	There are no current images available to make an assessment for this site. Most up-to-date image is 02 July 2019.	P	0	2-Jul-19	Left
Shabelle Middle	Balad	Buulo-Raqi	2.46398	45.46829	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	Cm	0	5-Jul-19	Left
Shabelle Middle	Balad	Fidi-Qalale	2.452021	45.467128	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	Co	0	5-Jul-19	Left
Shabelle Middle	Balad	Buulo Shiih	2.47235	45.46722	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019. Site is considered closed.	Co	0	5-Jul-19	Right
Shabelle Middle	Balad	War- Gaab	2.42552	45.46096	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	Co	0	5-Jul-19	Left
Shabelle Middle	Balad	Buulo-Shiih	2.471014	45.466983	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019. Site is considered closed.	Co	0	5-Jul-19	Right
Shabelle Middle	Balad	Mukuley	2.483167	45.485206	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	Cs	0	5-Jul-19	Left
Shabelle Middle	Balad	Mukudheere	2.44199	45.46552	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	Cs	0	5-Jul-19	Left
Shabelle Middle	Balad	Dhagaxow	2.521923737	45.48852449	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	Cs	0	5-Jul-19	Right
Shabelle Middle	Balad	Buulo Shiih	2.471729425	45.47305044	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	Cs	0	5-Jul-19	Right

Shabelle Middle	Balad	Muku Dheere	2.43538	45.46735	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	O	12	5-Jul-19	Left
Shabelle Middle	Balad	Buulo Shiikh	2.471485	45.472728	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	P	0	5-Jul-19	Left
Shabelle Middle	Balad	Buulo-Raaxo	2.454932	45.466077	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	P	0	5-Jul-19	Left
Shabelle Middle	Balad	Fidi-Qalale	2.450243	45.466218	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	P	0	5-Jul-19	Left
Shabelle Middle	Balad	Buulo Shiikh	2.471938905	45.46825626	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	P	0	5-Jul-19	Right
Shabelle Middle	Balad	Mukuley	2.485739	45.483909	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	P	0	5-Jul-19	Left
Shabelle Middle	Balad	Buulo-Raqi	2.46124	45.46594	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	P	0	5-Jul-19	Left
Shabelle Middle	Balad	Buulo Shiikh	2.472935269	45.47661753	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	P	0	5-Jul-19	Left
Shabelle Middle	Balad	Muku Dheere	2.438322616	45.46551347	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	P	0	5-Jul-19	Left
Shabelle Middle	Balad	Fidi-Qalale	2.435644659	45.46428577	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	P	0	5-Jul-19	Right
Shabelle Middle	Balad	Muku Dheere	2.436892163	45.46726762	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	P	0	5-Jul-19	Left
Shabelle Middle	Balad	Yaaqle	2.50795	45.487261	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Cm	0	6-Jul-19	Right
Shabelle Middle	Balad	Xawaadley	2.58011	45.49006	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Cm	0	6-Jul-19	Right
Shabelle Middle	Balad	Farbaraako	2.513523	45.492291	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Cm	0	6-Jul-19	Left
Shabelle Middle	Balad	Maqdas	2.58466	45.497962	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Cm	0	6-Jul-19	Left
Shabelle Middle	Balad	Maqdas	2.59592912	45.49882601	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Cm	0	6-Jul-19	Left
Shabelle Middle	Balad	Buulo Shiikh	2.517699	45.494107	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Co	0	6-Jul-19	Left
Shabelle Middle	Balad	Shanlow	2.554417	45.489122	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Co	0	6-Jul-19	Right
Shabelle Middle	Balad	Sheekh Hintire	2.55643	45.49276	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Co	0	6-Jul-19	Left
Shabelle Middle	Balad	Shanlow	2.54876	45.49316	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Co	0	6-Jul-19	Left
Shabelle Middle	Balad	Raqeylow	2.594462	45.497225	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Co	0	6-Jul-19	Right
Shabelle Middle	Balad	Maqdas	2.588986	45.498671	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Co	0	6-Jul-19	Right
Shabelle Middle	Balad	Raqeylow	2.600693	45.501048	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Co	0	6-Jul-19	Left
Shabelle Middle	Balad	Raqeylow	2.604292044	45.50275757	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Co	0	6-Jul-19	Left
Shabelle Middle	Balad	Maqdas	2.584125033	45.49812618	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Co	0	6-Jul-19	Left
Shabelle Middle	Balad	Shanlow	2.54591	45.488045	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Cs	0	6-Jul-19	Right
Shabelle Middle	Balad	Jameeco- Misr	2.562741	45.49019	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Cs	0	6-Jul-19	Right
Shabelle Middle	Balad	Xawaadley	2.578438	45.494118	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Cs	0	6-Jul-19	Left
Shabelle Middle	Balad	Jameeco-Misr	2.573863	45.495442	There are no current images available to make an assessment for this site. Most up-to-date image is 06 July 2019.	Cs	0	6-Jul-19	Left
Shabelle Middle	Balad	Sheekh Hintire	2.56202	45.49687	There are no current images available to make an assessment for this site. Most up-to-date image is 02 July 2019.	O	7	6-Jul-19	Left
Shabelle Middle	Balad	Fidi-Qalale	2.435506556	45.46702875	There are no current images available to make an assessment for this site. Most up-to-date image is 05 July 2019.	P	0	6-Jul-19	Left
Hiraan	Jalalaqsi	Buulo Cali	3.2728	45.543272	There is a breakage at this point noted in the image of 07 December 2019. There is flooding on the nearby farms resulting from this site.	O	11	7/12/2019	Left
Hiraan	Jalalaqsi	Bacadley	3.290582	45.556813	There was no evidence of flooding nor of an intervention. Current images are needed. Most current image is of 03 Sept 2019.	O	9	3-Sep-19	Right
Shabelle Lower	Kurtunwaarey	Carmoy	1.661355027	44.38653499	There are no current images available to make an assessment for this site. Most up-to-date image is 03 September 2019.	P	0	3-Sep-19	Right
Hiraan	Jalalaqsi	Bacadley	3.288	45.558945	There are no current images available to make an assessment for this site. Most up-to-date image is 03 September 2019 which shows low river embankments.	POF	0	3-Sep-19	Left
Hiraan	Jalalaqsi	Mohamad Baroole	3.286941	45.55046	This part of the embankment is vulnerable when river levels rise. Current images are needed. Most current image is 03 September 2019.	POF	0	3-Sep-19	Left
Hiraan	Jalalaqsi	Helo-Banaan	3.29085	45.55366	There was no evidence of flooding nor of an intervention. Current images are needed. Most current image is of 03 Sept 2019.	POF	0	3-Sep-19	Left
Hiraan	Bulo Burto	Xamiir Gaab	3.630173472	45.66109568	There are no current images available to make an assessment for this site. Most up-to-date image is 25 September 2019.	P	0	25-Sep-19	Right
Hiraan	Bulo Burto	Afcad	3.601496765	45.66593973	This point should be monitored due to low river embankments as noted on the image of 10 February 2020.	POF	0	25-Sep-19	Left
Hiraan	Bulo Burto	Afcad	3.577929614	45.65922646	This point should be monitored due to low river embankments as noted on the image of 25 September 2019.	POF	0	25-Sep-19	Left
Hiraan	Bulo Burto	Ceel bacad	3.70078	45.67658	up-to-date image is 25 September 2019. Succeeding images of November 2019 are too cloudy to carry out any assessment.	POF	0	25-Sep-19	Left
Shabelle Middle	Jowhar	Mahadaay	2.96662	45.533606	There is no evidence of recent flooding noted at this site as at 11 October 2019. The site is considered closed.	Co	0	11-Oct-19	Left
Shabelle Middle	Jowhar	Shaam	2.98746	45.51821	evidence of water overflow into the nearby area noted in in the image of 11 Oct 2019.	Of	140	11-Oct-19	Right
Shabelle Middle	Jowhar	Shaam	2.98156	45.52019	evidence of water overflow for about 66m downstream, from this point that resulted to flooding into the nearby farms noted in the image of 11 Oct 2019.	Of	66	11-Oct-19	Right
Shabelle Middle	Jowhar	Hilo Axmadey	2.97277	45.52887	this point. This part of the embankment is vulnerable when river levels rise as noted in the image of 11 October 2019.	Of	200	11-Oct-19	Left
Shabelle Lower	Qoryooley	Kaaytoy	1.794922	44.665841	There are no current images available to make an assessment for this site. Most up-to-date image is 16 October 2019.	Cs	0	16-Oct-19	Left
Hiraan	Belet Weyne	Sagaarow	4.64051	45.2314	There is an open breakage at this point as noted on the image of 16 October 2019.	O	19	16-Oct-19	Right
Hiraan	Belet Weyne	Maclow	4.634264053	45.23866662	Vegetation cover hinders accurate assessment of this point as noted on 29 February 2020	POF	0	16-Oct-19	Left
Shabelle Lower	Qoryooley	Tugaarrey	1.894457327	44.75976525	evidence of water spilling into the nearby farms noted in the image of 20 October 2019.	P	0	20-Oct-19	Left
Shabelle Lower	Qoryooley	Siimow	1.79093	44.6406	There is no evidence of flooding at this site as at 20 October 2019.	P	0	20-Oct-19	Right
Hiraan	Belet Weyne	Hoyin	4.650604	45.229824	This point should be monitored due to low river embankments as noted on the image of 29 February 2020	POF	0	20-Oct-19	Right

Shabelle Lower	Qoryooley	Marera	1.91966	44.777835	October 2019 shows evidence of flooding in the nearby area. The points are canal intakes and need monitoring.	cm	0	27-Oct-19	Right
Shabelle Lower	Qoryooley	Mubaarak	1.916139	44.776232	image of 27 Oct 2019. There is evidence of flooding noted in the image of 27 October 2019.	P	0	27-Oct-19	Right
Shabelle Lower	Qoryooley	Labaajo	1.849113911	44.70800895	There are no current images available to make an assessment for this site. Most up-to-date image is 28 October 2019.	P	0	28-Oct-19	Right
Shabelle Lower	Qoryooley	Sigaale bari	1.84904	44.7081	The embankment are very low as noted on 28 October 2019	P	0	28-Oct-19	Left
Hiraan	Bulo Burto	Sheybow	3.74515	45.61838	A breakage at this point caused flooding into the nearby farms as noted in the image of 02 November 2019	O	13	2-Nov-19	Right
Hiraan	Bulo Burto	Ceel bacad	3.69629	45.67867	resulted to flooding in the nearby farms. This is noted in the image of 02 November 2019.	Of	40	2-Nov-19	Left
Hiraan	Bulo Burto	Goonyaale	3.67125	45.67083	In the image of 02 November 2019 shows water overflow flooding the nearby farms.	Of	74	2-Nov-19	Right
Hiraan	Bulo Burto	Jaaboole Bari	3.815634856	45.56519299	image of 10 Nov 19 there was water overflow at the same point causing more floods in the area.	O	25	10-Nov-19	Right
Hiraan	Bulo Burto	Daharro	3.883	45.56188	From this point and about 300m upstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	300	10-Nov-19	Right
Hiraan	Bulo Burto	Daharro	3.88237	45.56261	From this point and about 100m upstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	100	10-Nov-19	Left
Hiraan	Bulo Burto	Dhayib	3.90115	45.57111	From this point and about 300m downstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	300	10-Nov-19	Left
Shabelle Lower	Afgooye	Aw Dheegle/October Malble	1.98555	44.83301	There is no evidence of flooding at this site as at 15 November 2019. The site is closed.	Co	0	11-Nov-19	Left
Shabelle Lower	Afgooye	Sabiid	2.129266	45.03829	There is no evidence of recent flooding at this point as at 15 November 2019. The site is closed.	Co	0	15-Nov-19	Right
Shabelle Lower	Qoryooley	Buulo-Maxamed Cumar	1.88838	44.74744	There is no evidence of flooding at this site as at 15 November 2019. The site can be considered closed.	Co	0	15-Nov-19	Left
Shabelle Lower	Qoryooley	Sadiq	1.90456	44.76325	There is no evidence of flooding at this site as at 15 November 2019. The site can be considered closed.	Co	0	15-Nov-19	Left
Shabelle Lower	Qoryooley	Dara Salaam	1.918453	44.787664	There is no evidence of flooding at this site as at 15 November 2019. The site is closed.	Co	0	15-Nov-19	Right
Shabelle Lower	Qoryooley	Dara Salaam	1.923762	44.788945	There is no evidence of flooding at this site as at 15 November 2019. The site is closed.	Co	0	15-Nov-19	Right
Shabelle Lower	Afgooye	Aw Dheegle/Caanoole	1.975886	44.833889	There is no evidence of flooding at this site as at 15 November 2019. The site is closed.	Co	0	15-Nov-19	Right
Shabelle Lower	Afgooye	Aw Dheegle/Caanoole	1.975893	44.835226	There is no evidence of flooding at this site as at 15 November 2019. The site is closed.	Co	0	15-Nov-19	Right
Shabelle Lower	Afgooye	Shaan	2.0271	44.86005	There is no evidence of recent flooding at this point as at 15 November 2019. The site is closed.	Co	0	15-Nov-19	Right
Shabelle Lower	Afgooye	Caanoole	2.130313	45.041304	There is no evidence of recent flooding at this point as at 15 November 2019. The site is closed.	Co	0	15-Nov-19	Right
Shabelle Lower	Afgooye	Mareerey	2.13622	45.05783	There is no evidence of recent flooding at this point as at 15 November 2019. The site is considered closed.	Co	0	15-Nov-19	Left
Shabelle Lower	Afgooye	Sabiid	2.128196	45.03722	The intervention is still intact. No signs of recent floods as at 15 November 2019.	Cs	0	15-Nov-19	Right
Shabelle Lower	Afgooye	Shaan	2.020637226	44.85728	The intervention is still intact at this site. No signs of recent floods as at 15 November 2019.	Cs	0	15-Nov-19	Left
Shabelle Lower	Afgooye	Aw Dheegle/October Malble	1.984016	44.831865	This part of the embankment is vulnerable as noted in the image of 06 November 2019. There is flooding in the nearby farms.	P	0	15-Nov-19	Left
Shabelle Lower	Qoryooley	Deg Yeroy	1.95535	44.82417	There is no evidence of flooding at this site as at 15 November 2019. The site is closed.	PO	0	15-Nov-19	Right
Shabelle Lower	Qoryooley	Qoriolle	1.80475	44.686	There is no evidence of flooding at this site as at 19 November 2019. The site can be considered closed.	Co	0	19-Nov-19	Left
Hiraan	Bulo Burto	Sheybow	3.75063	45.61504	A breakage at this point of the embankment caused flooding into the nearby farms as noted in the image of 02 November 2019.	O	4	22-Nov-19	Right
Shabelle Middle	Jowhar	Bayaxaaw	2.742863	45.498843	2019. An intervention using Soil heaping was implemented in January 2019. The intervention needs to be reinforced.	Of	100	1-Dec-19	Left
Shabelle Lower	Afgooye	Sagaalaad	2.141368	45.098205	There is no evidence of recent flooding at this point as at 03 December 2019. The site is considered closed.	Co	0	3-Dec-19	Right
Shabelle Lower	Afgooye	Blad-Aamin	2.120424	44.981533	There is no evidence of recent flooding at this point as at 03 December 2019. The site is closed.	Co	0	3-Dec-19	Left
Shabelle Lower	Afgooye	Mareerey	2.136589	45.055319	image of 09 November 2019. There is evidence of water spillage into the nearby area. There seems to be a sandbag intervention that is silted.	Of	0	3-Dec-19	Left
Hiraan	Belet Weyne	Gambarlawe	4.70243	45.20674	evidence of previous water overflow into the nearby area noted in the image of 04 December 2019. However, vegetation cover along the river bank hinders	Pof	0	4-Dec-19	Right
Shabelle Middle	Jowhar	Mahadaay	2.977004	45.530135	There is no evidence of recent flooding at this point as at 07 December 2019. A soil heaping intervention implemented in 2015 is still in place.	Cm	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Eji	3.184367	45.537806	There is no evidence of recent flooding at this site as at 07 Dec 2019. Intervention done in 2017 could still be intact.	Cm	0	7-Dec-19	Right
Shabelle Middle	Jowhar	Duduble	3.139851645	45.54244911	There is no evidence of recent flooding at this site as at 07 December 2019.	Cm	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Axmed Cigoow	2.901694	45.551127	There is no evidence of flooding at this site as at 19 December 2019. Intervention implemented in January 2019 could still be intact.	Cm	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Cadiimale	2.93642974	45.53339456	There is no evidence of recent flooding at this site as at December 2019. The site can be considered closed.	Cm	0	7-Dec-19	Right
Shabelle Middle	Jowhar	Kulmis	2.936788758	45.53353717	There is no evidence of recent flooding at this site as at December 2019. The site can be considered closed.	Cm	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Buulo axmed	2.89779	45.54783	Vegetation cover at this part hinders accurate assessment. The site could be closed.	Cm	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Duduble	3.15128	45.55525	There is no current image to make an assessment for this site. Most current image is of 25 February 2019.	Cm	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Eji	3.18262	45.5375	There is no evidence of recent flooding at this site as at 07 December 2019. Intervention done in January 2019 is still intact.	Cm	0	7-Dec-19	Right
Shabelle Middle	Jowhar	Kulmis	2.935842	45.533068	There is no evidence of recent flooding at this site as at December 2019. The site can be considered closed.	Co	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Barrey	2.938601	45.53325	There is no evidence of recent flooding at this site as at December 2019. The site can be considered closed.	Co	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Barrey	2.938006	45.533585	There is no evidence of recent flooding at this site as at December 2019. The site can be considered closed.	Co	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Hilo Axmadey	2.96896	45.52094	There is no evidence of recent flooding at this part. Site is considered closed.	Co	0	7-Dec-19	Right
Shabelle Middle	Jowhar	Mahadaay	2.968537	45.529055	2019. Intervention implemented in March 2015 is still intact. Site is considered closed.	Co	0	7-Dec-19	Right
Shabelle Middle	Jowhar	Barrey	2.93876	45.5299	There is no evidence of recent flooding at this site as at December 2019. The site can be considered closed.	Co	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Sigaale bari	2.938406768	45.53337732	There is no evidence of recent flooding at this site as at December 2019. The site can be considered closed.	Co	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Shidlo Bari	2.94436	45.53258	There is no evidence of flooding at this sit. A sandbag intervention has been implemented and is still visible at 07 December 2019.	Cs	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Baaroweyne	2.95268	45.52998	There is no evidence of flooding at this sit. A sandbag intervention has been implemented and is still visible at 07 December 2019.	Cs	0	7-Dec-19	Right

Shabelle Middle	Jowhar	Xuddor	2.958004	45.530414	There is no evidence of flooding at this site. A sandbag intervention has been implemented and is still visible as at 07 December 2019.	Cs	0	7-Dec-19	Right
Shabelle Middle	Jowhar	Kulmis Weyne	2.931061	45.531584	Sandbag intervention implemented in January 2019 is still intact and visible as at 07 December 2019.	Cs	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Barrey	2.943554	45.53206	There is no evidence of flooding at this site. A sandbag intervention has been implemented and is still visible as at 07 December 2019.	Cs	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Kulmis-Weyne	2.93091	45.53068	Sandbag intervention implemented in January 2019 is still intact and visible as at 07 December 2019.	Cs	0	7-Dec-19	Right
Shabelle Middle	Jowhar	Barrey	2.945664	45.532811	There is no evidence of flooding at this site. A sandbag intervention has been implemented and is still visible as at 07 December 2019.	Cs	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Axmed Cigoow	2.90933	45.53888	Sandbag intervention implemented in January 2019 is still intact as at 07 December 2019.	Cs	0	7-Dec-19	Right
Shabelle Middle	Jowhar	Axmed Cigoow	2.908729	45.547681	Sandbag intervention implemented in January 2019 is still visible and intact as at 07 December 2019.	Cs	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Axmed Cigoow	2.907266	45.549211	Sandbag intervention implemented in January 2019 is still visible and intact as at 07 December 2019.	Cs	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Duduble	3.13748	45.53243	There is no evidence of recent flooding at this part of the embankment as at 07 December 2019.	Cs	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Duduble	3.15016	45.55468	There is no current image to make an assessment for this site. Most current image is of 25 February 2019.	Cs	0	7-Dec-19	Left
Hiraan	Jalalaqsi	Bukuraale	3.236672	45.537236	The site was closed using soil heaping in 2018. However, the breakage is broken again as this is the source of flooding as noted in the image of 07 Dec 2019.	O	9	7-Dec-19	Left
Hiraan	Jalalaqsi	Mohamud Baroole	3.290567	45.55157	There is evidence of flooding noted at this point as at 07 Dec 2019.	O	13	7-Dec-19	Left
Hiraan	Jalalaqsi	Bukuraale	3.239089183	45.53976186	There is a breakage at this part of the river embankment that has been open since 2017.	O	7	7-Dec-19	Right
Shabelle Middle	Jowhar	Duduble	3.148744683	45.53634048	Most current image of December 2019 was too cloudy to make any assessment.	O	3	7-Dec-19	Right
Shabelle Middle	Jowhar	Buulo axmed	2.90277	45.55137	the image of 07 December 2019. A sandbag intervention implemented in May 2018 is fully silted and needs to be implemented again.	O	5	7-Dec-19	Left
Shabelle Middle	Jowhar	Duduble	3.13648	45.53329	flooding in the nearby farms. There is no evidence of an intervention as at 07 December 2019.	O	3	7-Dec-19	Left
Shabelle Middle	Jowhar	Kab daydale	3.16392	45.53277	January 2019. However as seen in the image of 07 December 2019 the intervention has been washed away and there is a breakage that caused flooding	O	32	7-Dec-19	Right
Shabelle Middle	Jowhar	Hurway	3.116309	45.54678	There is no evidence of recent flooding nor of an intervention from this point as at 07 December 2019. Vegetation cover at this site hinders accurate assessment.	O	3	7-Dec-19	Right
Hiraan	Jalalaqsi	Afgooye	3.2472	45.5411	There is a breakage at this part of the river embankment. Water from this point caused floods into the near farms as noted in 07 december 2019.	O	4	7-Dec-19	Left
Hiraan	Jalalaqsi	Buulo-Mudul	3.27918	45.5449	There is a breakage at this point noted in the image of 07 December 2019. There is flooding on the nearby farms resulting from this breakage at this site.	O	13	7-Dec-19	Left
Hiraan	Jalalaqsi	Buulo Cali	3.26877	45.54697	There is a breakage at this point noted in the image of 07 December 2019.	O	4	7-Dec-19	Left
Hiraan	Jalalaqsi	Buulo Cali	3.26836	45.54905	There is a breakage at this point noted in the image of 07 December 2019. There is evidence of flooding noted in image of 07 Dec 2019 (Sand deposits).	O	10	7-Dec-19	Left
Hiraan	Jalalaqsi	Afgooye	3.25016	45.54831	There is a breakage at this point. There is evidence of flooding noted in the image of 07 Dec 2019.	O	4	7-Dec-19	Left
Hiraan	Jalalaqsi	Afgooye	3.24798	45.54196	There is a breakage at this point. There is evidence of flooding noted in the image of 07 Dec 2019.	O	2	7-Dec-19	Right
Hiraan	Jalalaqsi	Afgooye	3.24747	45.54153	image of 07 Dec 2019. Water from this point has caused flooding in the nearby farms.	O	4	7-Dec-19	Left
Hiraan	Jalalaqsi	Afgooye	3.24242	45.54218	There is a breakage at this point of the river embankment. There is evidence of flooding on the nearby farms as noted in the image of 07 Dec 2019.	O	5	7-Dec-19	Right
Hiraan	Jalalaqsi	Bukuraale	3.23643	45.53678	There is an open breakage at this point that caused flooding as seen in the image of 07 Dec 2019.	O	3	7-Dec-19	Right
Hiraan	Jalalaqsi	Bukuraale	3.2364	45.53575	There is an open breakage at this point that caused flooding in the nearby farms as seen in the image of 07 Dec 2019.	O	14	7-Dec-19	Right
Hiraan	Jalalaqsi	Bukuraale	3.23692	45.53453	image of 07 Dec 2019. Water from this point caused flooding in the nearby farms.	O	10	7-Dec-19	Left
Hiraan	Jalalaqsi	Shirkadda	3.2335	45.53607	image of 07 Dec 2019. Water from this point caused flooding in the nearby farms.	O	6	7-Dec-19	Left
Hiraan	Jalalaqsi	Shirkadda	3.23194	45.53621	There is an open breakage at this point that has caused flooding in the nearby farms as seen in the image of 07 Dec 2019.	O	4	7-Dec-19	Left
Hiraan	Jalalaqsi	Diinlow	3.22233	45.53137	source of the waters flooding the nearby farms as noted in the image of 07 dec 2019.	O	4	7-Dec-19	Left
Hiraan	Jalalaqsi	Diinlow	3.22094	45.52779	source of the waters flooding the nearby farms as noted in the image of 07 Dec 2019.	O	2	7-Dec-19	Left
Hiraan	Jalalaqsi	Diinlow	3.22123	45.52716	source of the waters flooding the nearby farms as noted in the image of 07 Dec 2019.	O	2	7-Dec-19	Right
Shabelle Middle	Jowhar	Eji	3.1807	45.53445	source of the waters flooding the nearby farms as noted in the image of 07 Dec 2019.	O	4	7-Dec-19	Right
Shabelle Middle	Jowhar	Eji	3.18022	45.53405	source of the waters flooding the nearby farms as noted in the image of 07 Dec 2019.	O	5	7-Dec-19	Left
Shabelle Middle	Jowhar	Eji	3.17752	45.53247	source of the waters flooding the nearby farms as noted in the image of 07 Dec 2019.	O	18	7-Dec-19	Left
Shabelle Middle	Jowhar	Eji	3.17477	45.53213	source of the waters flooding the nearby farms as noted in the image of 07 Dec 2019.	O	12	7-Dec-19	Left
Shabelle Middle	Jowhar	Kab Daydale	3.16088	45.52713	This point is part of a canal. There is a breakage at this point that caused flooding in the nearby farms as noted in the image of 07 Dec 2019.	O	3	7-Dec-19	Left
Shabelle Middle	Jowhar	Duduble	3.14407	45.53278	The nearby farms were flooded with water that originated from this point as noted in the image of 07 December 2019.	O	14	7-Dec-19	Left
Shabelle Middle	Jowhar	Xuddor	2.96077	45.53361	source of the waters flooding the nearby farms as noted in the image of 11 October 2019.	O	10	7-Dec-19	Right
Shabelle Middle	Jowhar	Xuddor	2.95972	45.53356	source of the waters flooding the nearby farms as noted in the image of 11 October 2019.	O	11	7-Dec-19	Right
Shabelle Middle	Jowhar	Kulmis Weyne	2.93374	45.53121	There is a breakage at this part of the embankment. There is evidence of flooding noted in the image of 07 December 2019.	O	9	7-Dec-19	Left
Hiraan	Jalalaqsi	Bukuraale	3.23855	45.53988	evidence flooding into the nearby farms as noted in the image of 07 December 2019.	O	8	7-Dec-19	Right
Shabelle Middle	Jowhar	Kulmis-Weyne	2.933026	45.530862	A Sandbag intervention was implemented in 2018. There is evidence of flooding in this area noted in 7 Dec 2019. The intervention needs to be reinforced.	Of	10	7-Dec-19	Right
Shabelle Middle	Jowhar	Mahadaay	2.9675	45.53148	waters that have flooded the nearby area as seen in the image of 10 October 2019.	Of	112	7-Dec-19	Right
Shabelle Middle	Jowhar	Kulmis Weyne	2.92576	45.531771	11 October 2019. However, there is evidence of water overflow resulting from this part that has caused flooding into the nearby farms.	Of	22	7-Dec-19	Right
Hiraan	Jalalaqsi	Afgooye	3.245042	45.54118	image of 07 Dec 2019. Water from this point has caused flooding in the nearby farms.	Of	70	7-Dec-19	Left
Shabelle Middle	Jowhar	Diinlow	3.216186	45.530351	evidence of water overflow for about 250m downstream, from this point that resulted to flooding into the nearby farms noted in the image of 07 Dec 2019.	Of	250	7-Dec-19	Left
Hiraan	Jalalaqsi	Buulo Cali	3.258966	45.550144	noted in the image of 07 December 2019. The Overflow is noted for about 500m downstream affecting the nearby farms.	Of	500	7-Dec-19	Left
Shabelle Middle	Jowhar	Mahadaay	2.96901	45.52955	evidence of flooding at this part resulting from water overflow as noted in the image of 07 December 2019.	Of	115	7-Dec-19	Left

Hiraan	Jalalaqsi	Buulo-Mudul	3.27812	45.54498	There is a water overflow at this point of the embankment flooding the nearby farms noted in the image of 07 December 2019.	Of	47	7-Dec-19	Left
Hiraan	Jalalaqsi	Buulo-Mudul	3.27606	45.54518	This part of the embankment is vulnerable when river levels rise. There is evidence in the image of December 2019 of flooding (sand deposits).	Of	45	7-Dec-19	Left
Shabelle Middle	Jowhar	Hilo Axmadey	2.97016	45.5265	There is an overflow at this point as noted in the image of 07 December 2019 that has resulted into flooding in the nearby farms.	Of	300	7-Dec-19	Left
Shabelle Middle	Jowhar	Xaamshooley	2.91516	45.53547	There is evidence of water overflow at this part of the embankment that caused flooding into the nearby farms as noted in the image of 11 October 2019.	Of	66	7-Dec-19	Left
Shabelle Middle	Jowhar	Kulmis - Weyne	2.91849	45.53412	There is evidence of water overflow at this part of the embankment that caused flooding into the nearby farms as noted in the image of 11 October 2019.	Of	80	7-Dec-19	Right
Shabelle Middle	Jowhar	Axmed Cigoow	2.91175	45.53951	There is evidence of flooding noted at this part of the embankment as at 11 October 2019. This part of the river needs to be monitored and reinforced.	P	0	7-Dec-19	Right
Shabelle Middle	Jowhar	Eji	3.183101	45.537725	There is no evidence of recent flooding at this site as at 07 December 2019.	P	0	7-Dec-19	Left
Hiraan	Jalalaqsi	Bukuraale	3.240408	45.541449	This site is a canal intake. There is no evidence of flooding as at 07 December 2019.	P	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Mahadaay	2.976877689	45.52958206	evidence of water overflow noted in December 2019. The intervention needs to be reinforced.	P	0	7-Dec-19	Right
Shabelle Middle	Jowhar	Duduble	3.147209	45.535222	that is flowing into the town from this point. The site is vulnerable when river levels rise. This is noted as at 07 Dec 2019.	P	0	7-Dec-19	Right
Shabelle Middle	Jowhar	Hurway	3.11613	45.54671	There is no evidence of recent flooding nor of an intervention from this point as at 07 December 2019. Vegetation cover at this site hinders accurate assessment.	P	0	7-Dec-19	Left
Shabelle Middle	Jowhar	Hilo Axmadey	2.97097	45.52772	embarkments and evidence of previous flooding in the farms near this point and this could be the source as noted in the image of 11 Oct 2019.	POf	11	7-Dec-19	Left
Shabelle Middle	Jowhar	Axmed Cigoow	2.91497	45.53734	There is no evidence of flooding at this part as at 07 December 2019. This part needs to be monitored due to low river embankments.	POf	0	7-Dec-19	Left
Hiraan	Jalalaqsi	Afgooye	3.243145	45.542431	There was water overflow at this part of the river noted on the image of 07 December 2019	Of	400	7-Dec-19	Left
Hiraan	Jalalaqsi	Buulo Cali	3.264698	45.55038	evidence in the image of 07 December 2019 of previous flooding (sand deposits).	POf	0	7-Dec-19	Left
Hiraan	Jalalaqsi	Bacadley	3.286847	45.54578	cover, coupled with vegetation at the point, it makes it difficult to accurately assess the point	POf	0	7-Dec-19	Right
Hiraan	Jalalaqsi	Mohamud Baroole	3.288143	45.550114	This point should be monitored due to low river embankments as noted on the image of 03 September 2019.	POf	0	7-Dec-19	Left
Hiraan	Jalalaqsi	Buulo-Mudul	3.276289299	45.54351385	This part of the embankment is vulnerable when river levels rise. There is evidence in the image of December 2019 of flooding (sand deposits).	POf	0	7-Dec-19	Right
Hiraan	Jalalaqsi	Buulo Cali	3.26854	45.54595	There is an overflow at this point of the embankment flooding the nearby farms noted in the image of 07 December 2019.	Of	1300	7-Dec-19	Right
Shabelle Lower	Qoryooley	Dhaayaney	1.80254298	44.65405599	There is no evidence of flooding at this site as at 10 December 2019. The site can be considered closed.	Co	0	10-Dec-19	Right
Hiraan	Bulo Burto	Jaaboole Bari	3.822141	45.562901	farms as noted in the image of 10 November 2019. The most recent image is 10 December 2019 which is full of clouds	O	8	10-Dec-19	Right
Hiraan	Bulo Burto	Helo-Banaan	4.125762686	45.48440814	There is a breakage at this part as noted in 10 December 2019. From this point water flooded into the nearby farms as noted.	O	15	10-Dec-19	Right
Hiraan	Bulo Burto	Bulo Burto	3.857651569	45.56684081	A breakage at this point of the embankment caused flooding into the nearby farms and the town as noted in the image of 10 November 2019.	O	9	10-Dec-19	Right
Hiraan	Bulo Burto	Jaaboole	3.82549	45.56377	A breakage at this point of the embankment caused flooding into the nearby farms as noted in the image of 10 November 2019.	O	12	10-Dec-19	Right
Hiraan	Bulo Burto	Dhayib	3.91371	45.57017	into the farms as seen in the image of 10 November 2019. This part looks like a be a slipway from the river.	O	9	10-Dec-19	Left
Hiraan	Bulo Burto	Xaaji Xoor	3.805419	45.577058	noted in the image of 10 November 2019 that resulted to flooding in the nearby farms.	O	23	10-Dec-19	Right
Hiraan	Bulo Burto	Xaaji Xoor	3.806685086	45.57356123	At this part of the embankment, there is evidence of water overflow noted in the image of 10 November 2019 that resulted to flooding in the nearby farms.	Of	100	10-Dec-19	Right
Hiraan	Jalalaqsi	Qoriley	3.538977255	45.64817257	There is evidence of water overflow causing flooding at this part of the embankment (sand deposits) noted in the image of 10 December 2019.	Of	150	10-Dec-19	Right
Hiraan	Bulo Burto	Goonyaale	3.66814	45.65684	image of 10 December 2019 there was water overflow flooding into the nearby farms.	Of	100	10-Dec-19	Left
Hiraan	Bulo Burto	Dufaley	3.66707	45.65405	image of 10 December 2019 there was water overflow flooding into the nearby farms.	Of	200	10-Dec-19	Left
Hiraan	Bulo Burto	Xaaji Xoor	3.80578	45.57512	From this point and about 170m upstream there was water overflow into the nearby farms causing floods as seen in the image of 11 December 2019.	Of	170	10-Dec-19	Left
Hiraan	Bulo Burto	Xaaji Xoor	3.80894	45.58182	A water overflow at this point of the embankment caused flooding into the nearby farms as noted in the image of 11 November 2019.	Of	23	10-Dec-19	Right
Hiraan	Bulo Burto	Xaaji Xoor	3.80978	45.58172	From this point and about 80m downstream there was water overflow into the nearby farms causing floods as seen in the image of 11 December 2019.	Of	80	10-Dec-19	Right
Hiraan	Bulo Burto	Jaaboole Bari	3.81623	45.56457	From this point and about 80m downstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	340	10-Dec-19	Right
Hiraan	Bulo Burto	Jaaboole Bari	3.81721	45.56461	From this point and about 500m downstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019.	Of	500	10-Dec-19	Left
Hiraan	Bulo Burto	Jaaboole	3.82669	45.56426	From this point and about 500m upstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	500	10-Dec-19	Right
Hiraan	Bulo Burto	Buulo Dacar	3.83048	45.56787	From this point and about 280m upstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	280	10-Dec-19	Right
Hiraan	Bulo Burto	Bulo Caro	3.83241	45.56881	From this point and about 250m upstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	250	10-Dec-19	Left
Hiraan	Bulo Burto	Bulo Caro	3.83988	45.57316	nearby farms causing floods as seen in the image of 10 November 2019. There was an overflow on the oppsite of this point.	Of	50	10-Dec-19	Left
Hiraan	Bulo Burto	Bulo Caro	3.83978	45.57322	From this point and about 1.1km upstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	1100	10-Dec-19	Left
Hiraan	Bulo Burto	Bananey	3.85413	45.57493	From this point and about 800m upstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	800	10-Dec-19	Left
Hiraan	Bulo Burto	C. Xaaseey	3.86132	45.56529	From this point and about 300m upstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	300	10-Dec-19	Left
Hiraan	Bulo Burto	C. Xaaseey	3.86131	45.56289	From this point and about 800m upstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	800	10-Dec-19	Right
Hiraan	Bulo Burto	Daharro	3.87128	45.56012	From this point and about 150m upstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	150	10-Dec-19	Right
Hiraan	Bulo Burto	Daharro	3.8722	45.56342	From this point and about 400m downstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	400	10-Dec-19	Left
Hiraan	Bulo Burto	Daharro	3.87382	45.5631	From this point and about 250m upstream there was water overflow into the nearby farms causing floods as seen in the image of 10 November 2019	Of	250	10-Dec-19	Right
Shabelle Lower	Qoryooley	Siimow	1.79207	44.64083	This point is a canal intake as noted on 25 September 2019	P	0	10-Dec-19	Left
Shabelle Lower	Qoryooley	Shaan	1.773666871	44.62994594	There is no evidence of flooding at this site as at 10 December 2019.	P	0	10-Dec-19	Left
Shabelle Lower	Qoryooley	Siimow	1.79338	44.6417	There more current image is 10 December 2019 and it is full of clouds	P	0	10-Dec-19	Left
Hiraan	Bulo Burto	Helo - Banaan	4.12418	45.49463	and very low river embankments noted in the image of 10 December 2019 (sand deposits) that resulted to flooding in the nearby farms.	POf		10-Dec-19	Right
Hiraan	Bulo Burto	Helo-Banaan	4.13044	45.48545	10 December 2019. The part of the embankment is vulnerable when river levels rise.	POf	0	10-Dec-19	Right

Hiraan	Belet Weyne	Ooda-Dheer	4.72984	45.22583	source of the waters flooding the nearby farms as noted in the image of 12 Dec 2019.	O	25	12-Dec-19	Right
Hiraan	Jalalaqsi	Buulo Qodaxleey	3.44625	45.62908	There is an overflow from this point of the river embankment. Evidence of flooding (sand deposits) is noted in the image of 27 December 2019.	Of	78	12-Dec-19	Right
Shabelle Middle	Jowhar	Muryaale	2.877691	45.535081	There is no evidence of flooding at this site as at 19 December 2019. Intervention implemented in 2019 could still be intact.	Cm	0	19-Dec-19	Left
Shabelle Middle	Jowhar	Sabuun	2.883048	45.537023	There is no evidence of flooding at this site as at 19 December 2019. Intervention implemented in January 2019 could still be intact.	Cm	0	19-Dec-19	Right
Shabelle Middle	Jowhar	Sabuun	2.88362	45.53752	There is no evidence of flooding at this site as at 19 December 2019. Intervention implemented in January 2019 could still be intact.	Cm	0	19-Dec-19	Right
Shabelle Middle	Jowhar	Kulmis Weyne	2.930782785	45.53256067	Sandbag intervention implemented in January 2019 is still intact and visible as at 11 October 2019. Succeeding images of December 2019 are too cloudy.	Cs	0	19-Dec-19	Left
Shabelle Middle	Balad	War- Gaab	2.421398147	45.45841705	This part is a canal opening. In the image of December 2019 there is evidence of flooding on the nearby farms. The canal needs to be reinforced.	O	2	19-Dec-19	Left
Shabelle Lower	Qoryooley	Tawakal	1.78732	44.63595	There is no evidence of flooding at this site as at 10 December 2019. Intervention could still be intact.	Cs	0	20-Dec-19	Left
Shabelle Lower	Qoryooley	Cadiimale	1.80214	44.6552	There more current image is 10 December 2019 and it is full of clouds	P	0	20-Dec-19	Right
Hiraan	Belet Weyne	Hilo Kelyo	4.788762	45.216166	There is a breakage at this point. Water from here resulted to flooding into the nearby farms as noted in the image of 26 December 2019.	O	6	26-Dec-19	Left
Hiraan	Belet Weyne	Doonsubagle	4.72454	45.19842	There is a breakage at this part. This is a canal, there is flooding into the farms that originated from this point as noted in the image of 26 December 2019.	O	15	26-Dec-19	Left
Hiraan	Jalalaqsi	Dufaley	3.457158	45.648311	There is no evidence of recent flooding at this site as at 27 December 2019. The site is considered closed.	Co	0	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.37915	45.605	There is no evidence of recent flooding at this point as at December 2019. The site is considered closed.	Co	0	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.367781162	45.58555705	There is a breakage at this part of the embankment that has resulted to flooding on the nearby farms as seen in the image of 27 December 2019.	O	11	27-Dec-19	Right
Hiraan	Jalalaqsi	Mareerey	3.35006	45.57487	image of December 2019, a breakage at this part of embankment caused a water overflow caused flooding into the nearby farms.	O	3	27-Dec-19	Right
Hiraan	Jalalaqsi	Dirgoys	3.350847	45.575281	image of 27 December 2019, a breakage at this part of embankment caused a water overflow causing flooding into the nearby farms.	O	9	27-Dec-19	Left
Hiraan	Jalalaqsi	Baqdaad Bari	3.397870833	45.60567876	caused flooding into the nearby area. There is evidence sand deposits and water as at 27 December 2019.	O	10	27-Dec-19	Left
Hiraan	Jalalaqsi	Dufaley	3.45758	45.63889	There is a breakage at this point that caused flooding in the nearby area as noted in the image of 27 December 2019.	O	5	27-Dec-19	Left
Hiraan	Jalalaqsi	Baqdaad Bari	3.41152	45.61098	There is a breakage at this point. Water from here caused flooding into the nearby farms as noted in the image of 27 December 2019.	O	4	27-Dec-19	Left
Hiraan	Jalalaqsi	Baqdaad Bari	3.41042	45.61033	There is a breakage at this point. Water from here caused flooding into the nearby farms as noted in the image of 27 December 2019.	O	6	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.38956	45.61282	There is a breakage at this part of the embankment that caused flooding into the nearby farms as seen in the image of 27 December 2019.	O	4	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.36759	45.58538	image of December 2019, a breakage at this part of embankment caused a water overflow caused flooding into the nearby farms.	O	10	27-Dec-19	Right
Hiraan	Jalalaqsi	Dirgoys	3.34723	45.57552	image of December 2019, a breakage at this part of embankment caused a water overflow caused flooding into the nearby farms.	O	4	27-Dec-19	Right
Hiraan	Jalalaqsi	Dirgoys	3.34641	45.58024	image of December 2019, a breakage at this part of embankment caused a water overflow caused flooding into the nearby farms.	O	3	27-Dec-19	Left
Hiraan	Jalalaqsi	Dirgoys	3.34508	45.58107	December 2019, however, vegetation cover hinders clear assessment of the embankment	O	10	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.37352	45.59058	on the nearby farms as seen in the image of 27 December 2019. Vegetation cover hinders better assessment of the breakage.	O	10	27-Dec-19	Right
Hiraan	Jalalaqsi	Jalalaqsi	3.37816	45.59177	m water overflow that caused flooding into the nearby farms as noted in the image of 27 December 2019.	Of	750	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.36769	45.58811	m water overflow that caused flooding into the nearby farms as noted in the image of 27 December 2019.	Of	1000	27-Dec-19	Left
Hiraan	Jalalaqsi	Dirgoys	3.342733407	45.58103442	image of December 2019, a water overflow caused flooding into the nearby farms.	Of	140	27-Dec-19	Right
Hiraan	Jalalaqsi	Jalalaqsi	3.380275139	45.60298174	This part of the embankment is vulnerable when river levels rise. As noted in the image of December 2019, a water overflow caused flooding.	Of	300	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.380864	45.601493	This part of the embankment is vulnerable and caused flooding into the nearby farms as noted in the image of 27 December 2019.	Of	43	27-Dec-19	Right
Hiraan	Jalalaqsi	Buulo Qodaxleey	3.444124	45.625491	December 2019 there is evidence of water overflow at this point that caused flooding into the nearby farms.	Of	80	27-Dec-19	Left
Hiraan	Jalalaqsi	Buulo Banaan	3.424642559	45.61376894	There was an overflow at this part of the embankment as seen in the image of 27 December 2019. The part is vulnerable when river levels rise.	Of	44	27-Dec-19	Left
Hiraan	Jalalaqsi	Baqdaad Bari	3.406639281	45.59624208	the nearby farms as seen in the image of 27 December 2019. The part is vulnerable when river levels rise.	Of	90	27-Dec-19	Left
Hiraan	Jalalaqsi	Bacadley	3.41025	45.59742	There was an overflow at this part of the embankment as seen in the image of December 2019. The part is vulnerable when river levels rise.	Of	85	27-Dec-19	Left
Shabelle Middle	Jowhar	Beerta siyago	3.02243	45.50514	form this point. This part of the embankment is vulnerable when river levels rise as noted in the image of 27 December 2019.	Of	70	27-Dec-19	Left
Hiraan	Jalalaqsi	Dirgoys	3.348887	45.575513	image of 27 December 2019, a water overflow caused flooding into the nearby farms.	Of	200	27-Dec-19	Left
Hiraan	Jalalaqsi	Dirgoys	3.35141	45.57456	image of December 2019, a water overflow caused flooding into the nearby farms.	Of	140	27-Dec-19	Right
Hiraan	Jalalaqsi	Dirgoys	3.35488	45.576884	image of 27 December 2019, a water overflow caused flooding into the nearby farms.	Of	24	27-Dec-19	Left
Hiraan	Jalalaqsi	Qurac-Jafle	3.336162	45.579753	image of 27 December 2019, a water overflow caused flooding into the nearby farms.	Of	200	27-Dec-19	Right
Hiraan	Jalalaqsi	Dirgoys	3.335313	45.580143	image of December 2019, a water overflow caused flooding into the nearby farms.	Of	200	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.382431	45.595445	This part of the embankment is vulnerable when river levels rise. As noted in the image of December 2019, a water overflow caused flooding.	Of	300	27-Dec-19	Left
Hiraan	Jalalaqsi	Buulo Qodaxleey	3.447295	45.630926	There is evidence of water overflow for about 400m down stream at this point that caused flooding into the nearby farms.	Of	400	27-Dec-19	Right
Hiraan	Jalalaqsi	Buulo Qodaxleey	3.447711	45.633914	There is evidence of water overflow that caused flooding (sand deposits) at this site noted in the image of 27 December 2019.	Of	100	27-Dec-19	Left
Hiraan	Jalalaqsi	Raqay	3.482537883	45.64733064	There is evidence of water overflow causing flooding at this part of the embankment (sand deposits) noted in the image of 27 December 2019.	Of	430	27-Dec-19	Right
Hiraan	Jalalaqsi	Jalalaqsi	3.391347754	45.60997568	This part of the embankment is vulnerable as seen in the image of 27 December 2019. An overflow from this part caused flooding into the nearby area.	Of	60	27-Dec-19	Right
Hiraan	Jalalaqsi	Buulo Cigalle	3.35597	45.5797	image of December 2019, a water overflow caused flooding into the nearby farms.	Of	63	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.37874	45.59129	This part of the embankment is vulnerable when river levels rise. As noted in the image of December 2019, a water overflow caused flooding.	Of	100	27-Dec-19	Right
Hiraan	Jalalaqsi	Jalalaqsi	3.38201	45.60959	This part of the embankment is vulnerable when river levels rise. As noted in the image of December 2019, a water overflow caused flooding.	Of	300	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.3891	45.61249	This part of the embankment is vulnerable as seen in the image of 27 December 2019. An overflow from this part caused flooding into the nearby area.	Of	45	27-Dec-19	Right
Shabelle Middle	Jowhar	Beerta siyago	3.02094	45.50859	This part of the embankment is vulnerable as noted in the image of 27 December 2019. There is evidence of recent flooding.	Of	21	27-Dec-19	Right

Hiraan	Jalalaqsi	Dufaley	3.45854	45.63658	downstream. There is evidence of flooding (sand deposits) noted in the image of 27 December 2019.	Of	130	27-Dec-19	Left
Hiraan	Jalalaqsi	Dufaley	3.45636	45.63723	There is evidence of flooding (sand deposits) noted in the image of 27 December 2019.	Of	125	27-Dec-19	Right
Hiraan	Jalalaqsi	Buulo Qodaxleey	3.45135	45.63144	There is evidence of flooding (sand deposits) noted in the image of 27 December 2019.	Of	66	27-Dec-19	Left
Hiraan	Jalalaqsi	Buulo Banaam	3.43795	45.61844	river embankment. This water caused flooding into the nearby farms as noted in the image of 27 December 2019.	Of	126	27-Dec-19	Left
Hiraan	Jalalaqsi	Buulo Qodaxleey	3.44147	45.62196	river embankment. This water caused flooding into the nearby farms as noted in the image of 27 December 2019.	Of	200	27-Dec-19	Right
Hiraan	Jalalaqsi	Jalalaqsi	3.39561	45.60639	From this point and 900m downstream there was water overflow into the nearby farms causing floods as seen in the image of 27 December 2019.	Of	900	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.37967	45.60512	image of 27 December 2019, a water overflow caused flooding into the nearby farms.	Of	14	27-Dec-19	Right
Hiraan	Jalalaqsi	Jalalaqsi	3.38074	45.60302	image of 27 December 2019, a water overflow caused flooding into the nearby farms.	Of	27	27-Dec-19	Right
Hiraan	Jalalaqsi	Jalalaqsi	3.36892	45.59085	image of December 2019, a water overflow caused flooding into the nearby farms.	Of	123	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.35799	45.58236	image of December 2019, a water overflow caused flooding into the nearby farms.	Of	60	27-Dec-19	Right
Hiraan	Jalalaqsi	Dirgoyis	3.34039	45.58037	image of December 2019, a water overflow caused flooding into the nearby farms.	Of	90	27-Dec-19	Right
Hiraan	Jalalaqsi	Dirgoyis	3.34128	45.58108	image of December 2019, a water overflow caused flooding into the nearby farms.	Of	85	27-Dec-19	Left
Hiraan	Jalalaqsi	Dufaley	3.45333	45.63491	There is evidence of water overflow causing flooding at this part of the embankment (sand deposits) noted in the image of 27 December 2019.	Of	33	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.3677	45.5881	There is evidence of water overflow at this part of the embankment that caused flooding into the nearby farms as noted in the image of 27 December 2019.	Of	1000	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.37099	45.59012	flooding about 180 m downstream into the nearby farms as noted in the image of 27 December 2019.	Of	500	27-Dec-19	Right
Shabelle Middle	Jowhar	Beerta siyago	3.00504	45.51218	evidence of flooding in the farms near this point and this could be the source as noted in the image of 27 Dec 2019.	P	0	27-Dec-19	Right
Hiraan	Jalalaqsi	Buulo Banaan	3.42539	45.61515	There is evidence of flooding at this part of the embankment as noted in the image of 27 December 2019. The area is vulnerable when river levels rise.	P	0	27-Dec-19	Left
Hiraan	Jalalaqsi	Dufaley	3.45335	45.6349	There is evidence of recent overflow (sand deposits) at this point as noted in the image of 27 December 2019. The part is vulnerable should river levels rise.	POf	0	27-Dec-19	Left
Hiraan	Jalalaqsi	Buulo Qodaxleey	3.45123	45.63135	There is evidence of previous water overflow causing flooding at this part of the embankment (sand deposits) noted in the image of 27 December 2019.	POf	0	27-Dec-19	Left
Hiraan	Jalalaqsi	Buulo Banaam	3.432026261	45.61790132	image of 27 December 2019.this point looks like a canal intake however, vegetation cover hinders accurate assessment.This point is a canal intake.	Of	900	27-Dec-19	Left
Shabelle Middle	Jowhar	Beerta siyago	3.02074	45.50761	There is no evidence of recent flooding at this part, however this point should be monitored due to low river embankments	POf	0	27-Dec-19	Right
Shabelle Middle	Jowhar	Beerta siyago	3.01533	45.50985	form this point. This part of the embankment is vulnerable when river levels rise as noted in the image of 27 December 2019.	POf	0	27-Dec-19	Left
Shabelle Middle	Jowhar	Beerta siyago	3.01121	45.51169	This part of the embankment is vulnerable as noted in the image of 27 December 2019. There is evidence of recent flooding.	POf	0	27-Dec-19	Left
Hiraan	Jalalaqsi	Buulo Cigalle	3.36084	45.5818	There is recent flooding at this point as at 27 December 2019 resulting to an over flow that strcthes 700m downstream	Of	700	27-Dec-19	Right
Hiraan	Jalalaqsi	Jalalaqsi	3.40287	45.60237	area is prone to water overflow as seen in images of June 2018 and December 2019.	POf	0	27-Dec-19	Left
Hiraan	Jalalaqsi	Jalalaqsi	3.40504	45.60125	area is prone to water overflow as seen in images of June 2018 and December 2019.	POf	0	27-Dec-19	Right
Hiraan	Jalalaqsi	Dufaley	3.45841	45.64664	There is evidence of flooding noted at this part in the image of 27 December 2019. The area is vulnerable when river levels rise.	POf	0	27-Dec-19	Right
Hiraan	Jalalaqsi	Jalalaqsi	3.383132	45.596135	There is no evidence of recent flooding at this point as at December 2019. The site is considered closed.	Co	0	29-Dec-19	Left
Shabelle Middle	Balad	Xagarow	2.42032355	45.44979638	There is no evidence of recent flooding at this part of the embankment as at 31 December 2019. Intervention implemented in 2017 is still intact.	Cm	0	31-Dec-19	Right
Shabelle Middle	Balad	War Gaab	2.420093026	45.43974268	This part is a canal opening. In the image of December 2019 there is evidence of flooding on the nearby farms. The canal needs to be reinforced.	O	2	31-Dec-19	Left
Shabelle Middle	Balad	Xagarow	2.41595	45.43124	There is an overflow at this point that extends 400m causing flooding into the nearby farms as seen in the image of 31 december2019.	Of	400	31-Dec-19	Right
Shabelle Middle	Balad	Xagarow	2.420436998	45.43996193	image of 31 December 2019, a water overflow caused flooding into the nearby farms. An intervention was implemented in 2017 needs to be reinforced.	Of	130	31-Dec-19	Right
Shabelle Middle	Balad	War Gaab	2.41955	45.44553	image of December 2019, a water overflow caused flooding into the nearby farms.	Of	68	31-Dec-19	Left
Shabelle Middle	Balad	War Gaab	2.4221	45.43779	From this point and 250m upstream, there is an overflow of water that resulted to flooding the nearby farms as noted in the image of 31 December 2019.	Of	250	31-Dec-19	Left
Shabelle Middle	Balad	Xagarow	2.41324	45.43225	resulted to flooding the nearby farms as noted in the image of 31 December 2019.	Of	120	31-Dec-19	Left
Shabelle Middle	Balad	War Gaab	2.42386	45.43861	At this point was water overflow as noted in the image of 31 December 2019. This resulted to flooding on the nearby farms.	Of	17	31-Dec-19	Right
Hiraan	Bulo Burto	Helo-Banaan	4.1241	45.50884	the image of 10 December 2019 (sand deposits) that resulted to flooding in the nearby farms.	Of	80	5-Jan-20	Right
Shabelle Middle	Balad	Kulmis Yerow	2.692732	45.510825	There is no evidence of recent flooding at this part of the embankment as at 06 January 2020.	Cm	0	6-Jan-20	Left
Shabelle Middle	Balad	Mandheere	2.70135	45.51102	There is no evidence of recent flooding at this site as at 06 January 2020. The site is considered closed.	Co	0	6-Jan-20	Left
Shabelle Middle	Balad	Raqayle	2.70533	45.51495	There is no evidence of recent flooding at this site as at 06 January 2020. The site is considered closed.	Co	0	6-Jan-20	Left
Shabelle Middle	Balad	Mandheere	2.695134	45.509446	Sandbag intervention implemented in January2017 is still intact and visible as at 06 January 2020.	Cs	0	6-Jan-20	Right
Shabelle Middle	Balad	Maagey	2.69036	45.50991	There is a breakage at this part of the embankment that has resulted to flooding on the nearby farms as seen in the image of 06 January 2020.	O	10	6-Jan-20	Right
Shabelle Middle	Balad	Raqayle	2.709768539	45.51451567	There is no evidence of recent flooding at this site as at 06 January 2020. The site is considered closed.	PO	0	6-Jan-20	Left
Shabelle Middle	Balad	Bayaxaaw	2.7324	45.49725	January 2020. Intervention implemented in April 2017 is still intact as at 10 January 2020.	Cm	0	10-Jan-20	Left
Shabelle Middle	Jowhar	Bayaxaaw	2.736616	45.500465	of14 October 2019. Source of the flooding is not very clear. However, the river embankment at this point needs to be reinforced.	Cm	0	10-Jan-20	Left
Shabelle Middle	Balad	Baqdaad	2.727349	45.505204	There is no evidence of recent flooding at this part of the embankment as at 06 January 2020.	Co	0	10-Jan-20	Left
Shabelle Middle	Balad	Balad	2.71595	45.51127	Sandbags intervention implemented in 2018 is still in place. The site is considered closed.	Co	0	10-Jan-20	Left
Shabelle Middle	Balad	Muukay	2.718399	45.511965	Machinery intervention implemented in 2017 is still in place. The site is considered closed.	Co	0	10-Jan-20	Right
Shabelle Middle	Balad	Jowhar	2.712734	45.514177	Sandbags intervention implemented in 2018 is still in place. The site is considered closed.	Co	0	10-Jan-20	Right
Shabelle Middle	Balad	Raqayle	2.721875	45.511054	There is no evidence of recent flooding at this site as at 10 January 2020. Sandbag intervention implemented in 2019 is still in place.	Cs	0	10-Jan-20	Right
Shabelle Middle	Balad	Bardheere	2.718493	45.511681	There is no evidence of recent flooding at this site as at 10 January 2020. Sandbag intervention implemented in 2019 is still in place.	Cs	0	10-Jan-20	Right

Shabelle Middle	Balad	Gaashaanle	2.72466	45.50914	2019. Vegetation cover hinders better assessment of the breakage. Sandbag intervention implemented in February 2018 needs to be reinforced.	P	0	10-Jan-20	Right
Shabelle Middle	Jowhar	Bayaxaaw	2.73911	45.5001	There is no evidence of recent flooding at this part of the embankment as at 10 January 2020.	PO	0	10-Jan-20	Left
Shabelle Middle	Jowhar	Timire	2.829661	45.534126	There is no evidence of recent flooding at this point as at 17 January 2020. Intervention implemented in 2018 is still intact.	Cm	0	17-Jan-20	Left
Hiraan	Belet Weyne	Belet Weyne	4.738627932	45.20627928	There is no evidence of recent flooding at this point as at 17 January 2020. Intervention implemented in 2018 is still intact.	Cm	0	17-Jan-20	Right
Hiraan	Belet Weyne	Belet Weyne	4.739214178	45.209586	There is no evidence of recent flooding at this point as at 17 January 2020. Intervention implemented in 2018 is still intact.	Cm	0	17-Jan-20	Left
Hiraan	Belet Weyne	Gambarlawe	4.694500175	45.20303126	There is no evidence of flooding originating from this point as at 17 January 2020. Intervention implemented in 2017 is still intact.	Cm	0	17-Jan-20	Right
Shabelle Middle	Balad	Muryaale	2.30682	45.35213	There is no evidence of recent flooding at this site as at 17 January 2020. The site is considered closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Maagey	2.77995	45.51342	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Raqayle	2.788172	45.5211	Intervention implemented in 2016 is still in place. The site can be considered closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Kalundi	2.79472	45.52202	Intervention implemented in 2016 is still in place. The site can be considered closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Kalundi 2	2.796613	45.523327	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Kalundi	2.797783	45.524207	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Xuddor	2.80621	45.53026	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Timire	2.80207	45.53056	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Timire	2.80583	45.53112	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Barey	2.81909	45.53566	Intervention implemented in 2016 is still in place. The site can be considered closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Barey	2.808923	45.535685	Intervention implemented in 2016 is still in place. The site can be considered closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Timire	2.811203	45.536056	Intervention implemented in 2016 is still in place. The site can be considered closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Bullo Geesaale	2.82018	45.537577	Intervention implemented in 2016 is still in place. The site can be considered closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Geedo Barkaan	2.812915	45.539086	Intervention implemented in 2016 is still in place. The site can be considered closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Moyka	2.749679	45.492504	January 2020. Intervention implemented in 2016 is still intact as at 10 January 2020. This site is closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Moyka	2.753982	45.494716	Intervention implemented in 2016 is still in place. The site can be considered closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Moyka	2.754952	45.494848	Intervention implemented in 2016 is still in place. The site can be considered closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Moyka	2.75136	45.49528	There is no evidence of recent flooding at this part as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Moyka	2.757827	45.497949	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Moyka	2.75688	45.49815	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Moyka	2.758232	45.49824	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Jowhar	2.774707	45.500977	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Moyka	2.75858	45.50125	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Biyasal/Jowhar	2.769928	45.501536	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Biyasa/Jowhar	2.77471	45.50182	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Biyasa	2.764389	45.502788	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Baalguri/Gacan Libaax	2.76853	45.50334	Sandbag intervention implemented in 2016 is still in place. The site can be considered closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Moyka	2.758744	45.503785	There is no evidence of recent floods at this point as at 17 January 2020. The site is closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Baalguri/Gacan Libaax	2.762924	45.506036	Sandbag intervention implemented in 2016 and reinforced in 2019 is still in place. The site can be considered closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Magadley	2.86046	45.52663	There is no evidence of recent floods at this point as at 10 January 2020. The site is closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Warai	2.83776	45.53571	There is no evidence of recent floods at this point as at 10 January 2020. The site is closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Gafay	2.847984	45.529391	There is no evidence of recent flooding at this site as at 17 January 2020. Sandbag intervention implemented in 2017 is still in place. The site is closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Warai	2.838713	45.534222	There is no evidence of recent flooding at this site as at 17 January 2020. Sandbag intervention implemented in 2016 is still in place. The site is closed.	Co	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Gaalay	2.844353	45.530105	There is no evidence of recent flooding at this site as at 17 January 2020. Sandbag intervention implemented in 2016 is still in place. The site is closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Gafay	2.84029	45.53087	There is no evidence of recent flooding at this site as at 17 January 2020. Sandbag intervention implemented in 2016 is still in place. The site is closed.	Co	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Gafay 3	2.843422446	45.53262321	There is no evidence of recent flooding at this site as at 17 January 2020. Sandbag intervention implemented in 2019 is still in place.	Cs	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Baaroweyne	2.864357	45.527666	There is no evidence of recent flooding at this site as at 17 January 2020. Sandbag intervention implemented in 2017 is still in place. The site is closed.	Cs	0	17-Jan-20	Left
Hiraan	Belet Weyne	Hilo Kelyo	4.785896263	45.20654096	Intervention using Sandbags intervention implemented in 2018 could still be intact.	Cs	0	17-Jan-20	Left
Hiraan	Belet Weyne	Doonsubagle	4.727965504	45.20323103	2018. In the image of 12 December 2019 there is evidence of water overflow. There is a sandbag intervention in the image of Dec 2019. Intervention needs to nearby farms as noted in the image of 12 December 2019. As at 17 January 2020 there is no evidence of an intervention.	Cs	0	17-Jan-20	Right
Hiraan	Belet Weyne	Xuubow	4.77261	45.18588	source of the waters flooding the nearby farms as noted in the image of 12 Dec 2019.	O	10	17-Jan-20	Right
Hiraan	Belet Weyne	Horseed	4.73339	45.22296	nearby farms as noted in the image of 12 December 2019. As at 17 January 2020 there is no evidence of an intervention.	O	14	17-Jan-20	Left
Hiraan	Belet Weyne	Xuubow	4.77864	45.18425	There is no evidence of an intervention.	O	7	17-Jan-20	Right
Shabelle Middle	Jowhar	Xaamshooley	2.87461	45.53968	This point is at a canal. In the image of 11 October 2019 there is evidence of water overflow at this part, flooding the nearby farms.	O	4	17-Jan-20	Left
Shabelle Middle	Jowhar	Kalundi	2.7949	45.52597	A breakage at this part noted in the image of 24 October 2019 and caused flooding of the nearby farms. This point however is near a road and not the river	O	24	17-Jan-20	Left
Shabelle Middle	Jowhar	Bayaxaaw	2.745443909	45.49732982	2019. An intervention using Soil heaping was implemented in January 2019. The Intervention needs to be reinforced.	Of	100	17-Jan-20	Left

Hiraan	Belet Weyne	Xuubow	4.77468	45.18344	part resulted to flooding into the nearby farms as seen in the images of 10 Oct 2019 and 12 Dec 2019. There is no evidence of an intervention as at 17 January	Of	70	17-Jan-20	Right
Hiraan	Belet Weyne	Billis diid	4.74829	45.19704	of 12 December 2019. Vegetation cover hinders accurate assessment. There was water overflow at this part that flooded the nearby farms.	Of	103	17-Jan-20	Right
Hiraan	Belet Weyne	Doonsubagle	4.72725	45.20094	seen in the image of 26 December 2019. There is an intervention, which needs to be reinforced.	Of	30	17-Jan-20	Right
Hiraan	Belet Weyne	Belet Weyne	4.73707	45.21892	that caused flooding in the nearby farms as seen in the image of 12 December 2019.	Of	280	17-Jan-20	Left
Hiraan	Belet Weyne	Xuubow	4.77804	45.18326	There is a breakage at this of the embankment that has resulted to flooding into the nearby area. Flooding is noted in the image of 12 December 2020.	Of	27	17-Jan-20	Right
Shabelle Middle	Jowhar	Garaash	2.74615	45.49543	There is evidence of water overflow causing flooding at this point noted in the image of 24 October 2019.	Of	100	17-Jan-20	Right
Shabelle Lower	Kurtunwaarey	Dacamaha	1.551174	44.128378	There is evidence of flooding noted in this area in the image of 17 January 2020. However, the source is the irrigation canals. These need to be reinforced.	P	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Kalundi	2.801908	45.524489	2016. However, in the image of 24 October 2019 there is evidence of flooding noted at this part. The intervention needs to be reinforced.	P	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Kalundi	2.799622	45.526317	image of 01 December 2019 there is evidence of flooding in this area. The embankment needs to be reinforced.	P	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Magadley	2.853777	45.528469	However, in the image of 11 October 2019 and 07 December 2019 there is evidence of flooding noted at this part. The river embankment needs to be	P	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Gafay	2.851209	45.529296	2016. However, in the image of 11 October 2019 there is evidence of flooding noted at this part. The intervention needs to be reinforced.	P	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Lama-Waab	2.86946	45.5332	07 December 2019. There is no evidence of an intervention as at 17 January 2020.	P	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Baaroweyne	2.869671	45.528887	There is evidence of flooding at this part noted in the image of 19 December 2020. An intervention was implemented in 2018 and needs to be reinforced.	P	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Gafay 3	2.84825	45.52934	2017. However, in the image of 11 October 2019 there is evidence of flooding noted at this part. The intervention needs to be reinforced.	P	0	17-Jan-20	Left
Shabelle Middle	Balad	Balcad	2.36294	45.39593	levels rise as note in 2016,2017 and 2018. However, there is no evidence of water overflow as at 20 January 2020.	P	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Lama-Waab	2.868413629	45.53260273	the image of 11 October 2019. However no evidence of flooding as at 17 Jan 2020.	P	0	17-Jan-20	Left
Hiraan	Belet Weyne	Doonsubagle	4.72903	45.20373	In the image of 12 December 2019 there is evidence of flooding at this part in the nearby areas. The part is vulnerable when river levels rise.	P	0	17-Jan-20	Right
Hiraan	Belet Weyne	Billis diid	4.74966	45.19215	This part of the river embankment is vulnerable should river levels rise as noted in the image of 12 December 2019.	P	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Kalundi 2	2.86819	45.52813	There is no evidence of recent flooding nor of an intervention at this part as at 17 January 2020. The area is still vulnerable should river levels rise.	POf	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Timire	2.825989	45.536803	This part of the embankment is vulnerable and water overflows flooding the nearby farms. The area is vulnerable when river levels rise.	POf	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Barey	2.825733	45.537248	This part of the embankment is vulnerable and water overflows flooding the nearby farms. The area is vulnerable when river levels rise.	POf	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Lama-Waab	2.86885	45.53019	This point should be monitored due to low river embankments as noted on the image of 7 december 2019.	POf	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Lama-Waab	2.868276	45.531496	In 2018, there was a water overflow from this part of the embankment. There is no evidence of recent flooding nor of an intervention as at 17 January 2020	POf	0	17-Jan-20	Left
Shabelle Middle	Jowhar	Lama-Waab	2.86844	45.53094	There is no evidence of recent flooding nor of an intervention at this part as at 17 January 2020.	POf	0	17-Jan-20	Left
Hiraan	Belet Weyne	Siigaalow	4.7576	45.19055	there is no evidence of an intervention at this part of the embankment as at 17 January 2020.	POf	0	17-Jan-20	Right
Shabelle Middle	Jowhar	Bullo Geesale	2.82456	45.53595	nearby farms. There is evidence of water collected on the farms noted in the image of 06 January 2020.	POf	0	17-Jan-20	Left
Hiraan	Belet Weyne	Siigaalow	4.750242	45.192075	There is no evidence of flooding at this part of the embankment as at 17 January 2020.	POf	0	17-Jan-20	Left
Hiraan	Belet Weyne	Horseed	4.733924	45.207231	There is no evidence of recent flooding nor of an intervention at this part as at 17 January 2020.	POf	0	17-Jan-20	Right
Shabelle Lower	Qoryooley	Islaaw	1.75871	44.62168	images of October and December 2019 are too cloudy. Accurate assessment for this site is not possible.	Cm	0	19-Jan-20	Left
Shabelle Lower	Qoryooley	Siimow	1.749295578	44.45165685	There is no evidence of flooding at this site as at 19 January 2020. Intervention implemented in 2017 could still be intact.	Cm	0	19-Jan-20	Right
Shabelle Lower	Qoryooley	Mashalaay	1.74408	44.5983	be a slipway for the canal to release excess water. There is what looks like a sluice gate as seen in the image of 20 December 2019.	Cm	0	19-Jan-20	Left
Shabelle Lower	Qoryooley	Mashalaay	1.74498	44.6001	be a slipway for the canal to release excess water. There is what looks like a sluice gate as seen in the image of 20 December 2019.	Cm	0	19-Jan-20	Right
Shabelle Lower	Qoryooley	Doon Loow	1.699603	44.444549	years however do not show evidence of flooding. We can consider the point closed. Reinforcement of the embankment however is recommended.	Co	0	19-Jan-20	Right
Shabelle Lower	Qoryooley	Bandar	1.735182547	44.44887606	There is no evidence of flooding at this site for the last 2 years and as at 19 January 2020. The site is considered closed.	Co	0	19-Jan-20	Right
Shabelle Lower	Qoryooley	Aesow	1.75029	44.60595	image of 20 December 2019. Vegetation cover at this point makes it difficult to make an accurate assessment as to the breakage point. This point is a canal	P	0	19-Jan-20	Left
Shabelle Lower	Qoryooley	Tugaarrey	1.756637815	44.61519877	There is no evidence of flooding at this site as at 19 January 2020.	P	0	19-Jan-20	Right
Shabelle Lower	Qoryooley	Khaliif	1.76339	44.6259	There is no evidence of flooding at this site as at 19 January 2020.	P	0	19-Jan-20	Left
Shabelle Lower	Qoryooley	Carfaale	1.74814	44.60267	20 December 2019 that could be from water overflow at the canals. The canals need to be reinforced.	P	0	19-Jan-20	Right
Shabelle Middle	Jowhar	Bayaxaaw	2.73402	45.50126	There is no evidence of recent floods at this point as at 10 January 2020. The site is considered closed.	Co	0	20-Jan-20	Left
Shabelle Lower	Kurtunwaarey	Dhaayaney	1.570068232	44.14979996	There is no evidence of flooding at this site for the last 2 years and as at 21 January 2020. The site is considered closed.	Co	0	21-Jan-20	Right
Shabelle Lower	Kurtunwaarey	Gees	1.570110043	44.15326012	There is evidence of flooding noted in the image of 21 January 2020. The flooding is next to the canals. The canals need to be rehabilitated.	P	0	21-Jan-20	Right
Shabelle Lower	Kurtunwaarey	Dacamaha	1.55347	44.13109	farms. However, these waters seem to be from the canals. The canals need to be rehabilitated.	P	0	21-Jan-20	Left
Shabelle Lower	Qoryooley	Bandar	1.766254	44.500558	This point is a canal intake. There is evidence of an intervention noted in the image of 22 January 2020. It could be a sluice gate.	Cm	0	22-Jan-20	Right
Shabelle Lower	Afgooye	Baloow	2.057441559	44.90767167	There is no evidence of recent flooding at this point as at 22 January 2020. The site is closed.	Cm	0	22-Jan-20	Left
Shabelle Lower	Qoryooley	Islaaw	1.769529187	44.50846444	This point is a canal intake. There is evidence of an intervention noted in the image of 22 January 2020. It could be a sluice gate.	Cm	0	22-Jan-20	Right
Shabelle Lower	Qoryooley	Degaybere	1.78136	44.53441	There is no evidence of flooding at this site for the last 2 years and as at 22 January 2020. The site is considered closed.	Co	0	22-Jan-20	Left
Shabelle Lower	Qoryooley	Faqayow	1.77785	44.55785	There is no evidence of flooding at this site for the last 2 years and as at 22 January 2020. The site is considered closed.	Co	0	22-Jan-20	Right
Shabelle Lower	Afgooye	Aray Mooy	2.20583	45.19874	There is no evidence of recent flooding at this site as at 22 January 2020. The site is considered closed.	Co	0	22-Jan-20	Left
Shabelle Lower	Afgooye	Shirkada	2.226179	45.20495	There is no evidence of recent flooding at this site as at 22 January 2020. The site is considered closed.	Co	0	22-Jan-20	Right
Shabelle Lower	Afgooye	Buulo-Madiina	2.227123	45.21381	There is no evidence of recent flooding at this site as at 22 January 2020. The site is considered closed.	Co	0	22-Jan-20	Right
Shabelle Lower	Afgooye	Sabyo Weyn	2.233259	45.22056	There is no evidence of recent flooding at this site as at 22 January 2020. The site considered closed.	Co	0	22-Jan-20	Left

Shabelle Lower	Afgooye	Qojjid	2.256852	45.225416	There is no evidence of recent flooding at this site as at 22 January 2020. The site considered closed.	Co	0	22-Jan-20	Right
Shabelle Lower	Afgooye	Beledulkariim	2.266825	45.229362	There is no evidence of recent flooding at this site as at 22 January 2020. The site considered closed.	Co	0	22-Jan-20	Left
Shabelle Lower	Afgooye	Sabyo	2.24478	45.23105	There is no evidence of recent flooding at this site as at 22 January 2020. The site considered closed.	Co	0	22-Jan-20	Left
Shabelle Lower	Afgooye	Banda Salaama	2.294206	45.262842	There is no evidence of recent flooding at this site as at 22 January 2020. The site considered closed.	Co	0	22-Jan-20	Right
Shabelle Lower	Afgooye	Walamooy	2.300749	45.326074	There is no evidence of recent flooding at this site as at 22 January 2020. The site considered closed.	Co	0	22-Jan-20	Left
Shabelle Lower	Afgooye	Bariire	2.05591	44.90789	recent flooding at this point from February 2018 to 22 January 2020. The site can be considered closed.	Co	0	22-Jan-20	Right
Shabelle Lower	Afgooye	Baloo	2.07226	44.90908	There is no evidence of recent flooding at this point as at 22 January 2020. The site is closed.	Co	0	22-Jan-20	Left
Shabelle Lower	Afgooye	Nuun	2.104819	44.908078	There is no evidence of recent flooding at this point as at 22 January 2020. The site is closed.	Co	0	22-Jan-20	Right
Shabelle Middle	Balad	Dohollei	2.298774626	45.3472121	There is no evidence of recent flooding at this site as at 22 January 2020. The site considered closed.	Co	0	22-Jan-20	Left
Shabelle Lower	Qoryooley	Islaaw	1.750596371	44.58094615	There is no evidence of flooding at this site for the last 2 years and as at 22 January 2020. The site is considered closed.	Co	0	22-Jan-20	Right
Shabelle Middle	Balad	Halgan	2.730692	45.496887	This point is a canal intake. Water has collected at the side of the canal. The canal walls need to be reinforced.	Cs	0	22-Jan-20	Right
Shabelle Middle	Balad	Balcad	2.36113	45.39683	This point is a canal intake. There is evidence of flooding in this farm that could have originated from this point noted in the image of 29 January 2020.	O	4	22-Jan-20	Right
Shabelle Lower	Afgooye	Tuulada Walamooy	2.29999	45.32346	The site has been considered closed previously but there is evidence of recent flooding at this point as noted in the image of 17 January 2020.	P	0	22-Jan-20	Left
Shabelle Lower	Afgooye	Berta Cali Haji	2.2237884	45.1993853	There is evidence of flooding near this point as seen in the image of January 2020. The source could be a canal intake. It needs to be reinforced.	P	0	22-Jan-20	Right
Shabelle Lower	Afgooye	Berta Shire Jiis	2.23173	45.21728	noted in the image of 22 January 2020 there is evidence of flooding in the nearby farms. The part can be vulnerable when river levels rise.	P	0	22-Jan-20	Right
Shabelle Lower	Afgooye	Walamooy	2.298949	45.323145	The site has been considered closed previously but there is evidence of recent flooding at this point as noted in the image of 17 January 2020.	P	0	22-Jan-20	Left
Shabelle Lower	Afgooye	Bariire	2.04606	44.89798	There is evidence of water spillage into the town from this part as noted in the image of 20 October 2019. This part is vulnerable should river levels rise.	P	0	22-Jan-20	Right
Shabelle Lower	Afgooye	Nuun	2.10551	44.91191	There is no evidence of recent flooding at this point as at 22 January 2020. The site is closed.	PO	0	22-Jan-20	Left
Shabelle Middle	Balad	Xagarow	2.422453097	45.43792621	There is no evidence of recent flooding at this site as at 26 January 2020. Intervention done could still be intact.	Cm	0	26-Jan-20	Right
Shabelle Middle	Balad	Xagarow	2.421337535	45.43406418	There is no evidence of recent flooding at this site as at 26 January 2020. Intervention done could still be intact.	Cs	0	26-Jan-20	Right
Shabelle Middle	Balad	War Gaab	2.410402	45.432238	There is no evidence of recent flooding at this site as at 26 January 2020. Intervention done could still be intact.	Cs	0	26-Jan-20	Left
Shabelle Middle	Balad	War Gaab	2.41971	45.44612	There is an overflow at this point as seen on the image of 31 december 2019 due to low embankments and a canal intake	Of	1500	26-Jan-20	Left
Shabelle Middle	Balad	Xagarow	2.41457	45.43229	There is an overflow at this point flooding nearby farms as seen in the image of 31 december 2019.	Of	130	26-Jan-20	Right
Shabelle Middle	Balad	Balcad	2.36197	45.39637	An intervention was done at this point in 2017. The intervention could still be intact though there is evidence of flooding noted in 29 January 2020.	Cm	0	29-Jan-20	Right
Shabelle Lower	Afgooye	Afgooye	2.143733	45.115728	The intervention is still intact. No signs of recent floods as at 29 January 2020.	Cm	0	29-Jan-20	Right
Shabelle Middle	Balad	Kurshaale	2.36024	45.4011	There is no evidence of flooding at this site as at 29 January 2020. Site is considered closed.	Co	0	29-Jan-20	Left
Shabelle Middle	Balad	Balcad	2.359719	45.390307	There is no evidence of flooding noted at this site as at the 29 January 2020. The site has been considered closed.	Co	0	29-Jan-20	Left
Shabelle Middle	Balad	Mareerey	2.386282201	45.41687325	There is no evidence of flooding nor of an intervention at this site since 2017. The site is considered closed.	Co	0	29-Jan-20	Right
Shabelle Middle	Balad	Mareerey	2.409921	45.422759	There is evidence of a Sandbag intervention along this canal as seen in the image of 29 January 2020.	Cs	0	29-Jan-20	Left
Shabelle Middle	Balad	Mareerey	2.390085	45.41851	January 2020. There is a visible Sandbag intervention visible in the image of 29 January 2020.	Cs	0	29-Jan-20	Left
Shabelle Middle	Balad	Mareerey	2.39038	45.41893	January 2020. Sandbag intervention was implemented in 2019 could still be intact.	Cs	0	29-Jan-20	Right
Shabelle Middle	Balad	Balcad	2.38859	45.42095	There is no evidence of flooding at this site as at 29 January 2020. There is evidence of sandbag intervention visible in the image of 29 January 2020.	Cs	0	29-Jan-20	Left
Shabelle Lower	Afgooye	Buulo-Folyo 1	2.13777	45.11208	This part of the embankment is vulnerable when river levels rise. As noted in the image of 03 December 2019 there was flooding into the nearby farms.	Of	160	29-Jan-20	Right
Shabelle Middle	Balad	Timire	2.37728	45.40795	There is no evidence of recent flooding at this site as at 29 January 2020.	P	0	29-Jan-20	Right
Shabelle Lower	Afgooye	Buulo-Folyo 1	2.137792	45.11278	however, the site needs to be monitored. There is some spillage into the nearby vegetation noted in the image of Dec 2019.	P	0	29-Jan-20	Left
Shabelle Middle	Balad	Mareerey	2.382169809	45.41144579	There is no evidence of recent flooding at this site as at 29 January 2020.	P	0	29-Jan-20	Left
Shabelle Middle	Balad	Balcad	2.366543767	45.40256287	There is no evidence of recent flooding at this site as at 29 January 2020.	P	0	29-Jan-20	Right
Shabelle Lower	Qoryooley	Majabto	1.757447724	44.62020609	Images of October and December 2019 are too cloudy. Accurate assessment is not possible.	P	0	29-Jan-20	Left
Shabelle Middle	Balad	Balcad	2.360379696	45.39920506	There is no evidence of flooding at this site as at 29 January 2020. The point is potential Old.	PO	0	29-Jan-20	Right
Shabelle Middle	Balad	Balcad	2.363125816	45.39617624	This site is a canal intake. There is no evidence of flooding as at the image of January 2020.	PO	0	29-Jan-20	Right
Shabelle Middle	Balad	Mareerey	2.388224	45.420469	29 January 2020, however, the point should be monitored due to low river embankments	POf	0	29-Jan-20	Right
Hiraan	Belet Weyne	Xuubow	4.781562	45.192876	image of 12 December 2019. This part of the embankment is vulnerable when river levels rise.	POf	0	4-Feb-20	Right
Hiraan	Belet Weyne	Buulo kahin	4.79792	45.18774	This point should be monitored because of low river embankments as noted on the image of 4 February 2020	POf	0	4-Feb-20	Right
Shabelle Lower	Afgooye	Balbaley	2.158368	45.131317	There is no evidence of recent floods at this point as at 05 February 2020. The site is closed.	Co	0	5-Feb-20	Left
Hiraan	Bulo Burto	Ladi gaduud	4.10302	45.52476	There is evidence of recent water overflow at this part as at 10 December 2019.	POf	0	5-Feb-20	Left
Hiraan	Bulo Burto	Aqablow	4.07396	45.51554	This point should be monitored due to low river embankments as seen on the image of 5 February 2010	POf	0	5-Feb-20	Right
Hiraan	Bulo Burto	Jameeco	4.12465	45.50295	2019. Water has accumulated in the nearby farms. The part of the embankment is vulnerable when river levels rise.	POf	0	5-Feb-20	Left
Hiraan	Bulo Burto	Jameeco	4.12582	45.49951	There is evidence of flooding at this point as seen in the image of December 2019. The part of the embankment is vulnerable when river levels rise.	POf	0	5-Feb-20	Left
Hiraan	Belet Weyne	Gambariawe	4.703305	45.204204	previous intervention with sand bags but flooding has broken through as noted in the image of 20 October 2019. As at February 2020 there is no evidence of an intervention.	O	10	7-Feb-20	Right
Hiraan	Belet Weyne	Belet Weyne	4.741253	45.211704	from this part flooding the town. As at February 2020 there is no evidence of an intervention.	O	11	7-Feb-20	Left
Hiraan	Belet Weyne	Doonsubagle	4.72398	45.19713	There is a breakage at this part. This is a canal, there is flooding into the farms that originated from this point as noted in the image of 26 December 2019.	O	28	7-Feb-20	Left

Hiraan	Belet Weyne	Doonsubagle	4.72117	45.19214	There is a breakage at this part. This is a canal, there is flooding into the farms that originated from this point as noted in the image of 26 December 2019.	O	22	7-Feb-20	Right
Hiraan	Belet Weyne	Bilis diid	4.74695	45.1955	intervention as seen in the image of 12 December 2019. The intervention needs to be reinforced.	O	4	7-Feb-20	Right
Hiraan	Belet Weyne	Bilis diid	4.75031	45.19148	There is a breakage at this part of the river embankment that resulted to flooding on to the nearby area as seen in the image of 12 December 2019.	O	6	7-Feb-20	Right
Shabelle Lower	Afgooye	Shaan	2.00991	44.845916	February 2020. intervention implemented in 2016 is still intact as at 10 January 2020. This site is closed.	Co	0	8-Feb-20	Left
Hiraan	Bulo Burto	Sheybow	3.74877	45.61563	the image of 02 November 2019,however, an intervention using sand bags is observed in the image of 10 February 2020	Cs		10-Feb-20	Right
Hiraan	Bulo Burto	Daharro	3.86942	45.5576	December 2019. It was the source of flooding as noted in the image of 10 November 2019.	O	14	10-Feb-20	Right
Hiraan	Jalalaqsi	Bur Dheer	3.503097	45.648959	This point is a breakage as noted in the image of 02 November 2019.	O	18	10-Feb-20	Right
Hiraan	Bulo Burto	Bulo Burto	3.854834143	45.57309247	A water overflow at this point of the embankment caused flooding into the nearby farms as noted in the image of 10 November 2019.	Of	21	10-Feb-20	Right
Hiraan	Bulo Burto	Goonyaale	3.66797	45.66539	in the image of 10 February 2020 ,low river embankments are noted.This point should be monitored due to very low river embankments	POf		10-Feb-20	Left
Hiraan	Bulo Burto	Goonyaale	3.66881	45.66002	In the image of 10 February 2020 ,low river embankments are noted.This point should be monitored due to very low river embankments	POf		10-Feb-20	Left
Hiraan	Jalalaqsi	Siibooy	3.56208	45.650821	This point should be monitored because of low river embankments as noted on the image of 10 February 2020	POf	0	10-Feb-20	Right
Hiraan	Bulo Burto	Ceel-Bacad	3.702160093	45.67126836	This point should be monitored due to low river embankments as noted on the image of 10 February 2020	POf	0	10-Feb-20	Left
Hiraan	Bulo Burto	Ooda-Dheer	3.689094501	45.67756162	This point should be monitored due to low river embankments as noted on the image of 10 February 2020	POf	0	10-Feb-20	Left
Hiraan	Bulo Burto	Ceel bacad	3.70538	45.66585	This point should be monitored due to low river embankments as seen on the image of 10 February 2020	POf	0	10-Feb-20	Right
Hiraan	Bulo Burto	Ceel bacad	3.70614	45.6689	This point has very low river embankments and evidence of previous overflow as noted on the image of 10 February 2020	POf	0	10-Feb-20	Left
Hiraan	Bulo Burto	Afcad	3.69063	45.6767	This point should be monitored because of low river embankments as noted on the image of 10 February 2020	POf	0	10-Feb-20	Left
Hiraan	Bulo Burto	Baqdaad Bari	3.6015	45.66076	This point should be monitored because of low river embankments as noted on the image of 10 February 2020	POf	0	10-Feb-20	Left
Shabelle Lower	Afgooye	Afgooye	2.146823	45.117093	the image of 06 November 2019. There is an intervention but the part looks vulnerable should river levels rise.	P	0	13-Feb-20	Right
Shabelle Lower	Afgooye	Balbaley	2.158897	45.130496	image of 12 February 2020.the most current image of 13 February 2020 is full of clouds	P	0	13-Feb-20	Left
Shabelle Lower	Afgooye	Sabyo Weyn	2.23072	45.21977	of 22 January 2020. Vegetation cover hinders assessment of the actual breakage point.	Of	300	13-Feb-20	Left
Shabelle Lower	Kurtunwaarey	Habaabshe	1.64646	44.34886	There is no evidence of recent flooding since the closure by sand bags as seen on the image of 26 November 2018.	Cs	20	24-Feb-20	Left
Shabelle Lower	Qoryooley	Cabdi abuur	1.717232	44.443266	This point is a canal intake which may overflow when river levels rises as seen on the most t up-to-date image of 24 Feb 2020.	O	6	24-Feb-20	Right
Shabelle Lower	Kurtunwaarey	Towfiik	1.657418363	44.26608652	Most current available image is of 24 February 2020 showing low embankments.	P	0	24-Feb-20	Right
Shabelle Lower	Kurtunwaarey	Towfiik	1.657045541	44.26558352	Most current available image is of 24 February 2020 showing low embankments.	P	0	24-Feb-20	Right
Hiraan	Belet Weyne	Gambarlawe	4.70199	45.20155	There is a breakage at this part of the embankment. There is evidence of flooding noted in the image of 04 December 2019.	O	8	29-Feb-20	Right
Hiraan	Belet Weyne	Qooqane	4.79325	45.20104	There is evidence of a recent overflow at this point as seen on the image of 29 February 2020.	POf	0	29-Feb-20	Right
Hiraan	Belet Weyne	Buulo kahin	4.78998	45.20716	This point should be monitored because of low river embankments as noted on the image of 4 February 2020	POf	0	29-Feb-20	Right
Shabelle Lower	Afgooye	Dhajalokh	2.179643	45.151617	There are no current images available to make an assessment for this site. Most up-to-date image is 11 June 2019.	Co	0	11-Jun-20	Left
Shabelle Lower	Kurtunwaarey	Dhaayaney	1.656510785	44.26271119	Current images are required to assess this site. Most current available image is of June 2018. The site had been closed using sandbags in 2017.	Cs	0	21-Jun-20	Right
Hiraan	Jalalaqsi	Buulo Cali	3.254078	45.547918	This part of the embankment is vulnerable at this part. There is evidence of flooding noted at this part as seen in the image of 07 Dec 2020. (Sand deposits)	Of	1000	7-Dec-20	Right